




10736.

SCHEME FOR MUG-3B - SEAFORTH GRAIN TERMINAL.

TO O L TION UT CD J5.	THE DESIGN AND MANUFACTURING INFORMATION CONTAINED IN THIS DRAWING IS THE EXCLUSIVE RIGHT OF BEWHURST & PARTNER LTD. AND MUST NOT BE COPIED OR USED FOR MANUFACTURING PURPOSES	ISSUE 1 2 3 4 8 8 7 8 9 10 11
	KEY DIAG. N°	DTX 361U/4
	EXT. DIAG. N° 5TX 361U	
	REL. DIAG. N°	
	PANEL LAYOUT N° HTX 361U	

DEWHURST & PARTNER LTD.
MELBOURNE WORKS. HOUNSLOW.

TITLE: SCHEME FOR MCC 3B SEAFORTH GRAIN TERMINAL

REVISION: 9
OVERSPEED
TIMER ADDE

ORIGIN: ICD
16/1/73 J

REVISION: 8
TRIPPER OVERLOAD
REPLACED BY LRI-
& MOL & LOL.

ORIGIN ICD
9/1/73 JS

REVISION: 7
INTERLOCKS FROM TRB6
MODIFIED ON LINES
52 & 553 0552 NOW
NO SO RELAY R85
CONTACTS NOW N/C
TAKE CCT MOD:
ORIGIN: SITE
7/12/72 JS.

SION: 6 LEAD INTERLOCK CCT TO OPEN CONTACTOR STOP RELAY CONTACT TO CABLE REEL	REVISION: 5 DESK TERMINAL ADDED.
N: ICD 72 JS.	ORIGIN: ICD. 1/2/72 SGD. JS

REVISION: 4
CHUTE BLOCK
INDICATION WAS
TO TERM 76

ORIGIN: EISP.
10/3/71 SGD. J.T.

REVISION: 3
GF3. 3AR, 3AF, &
CBR3 CONTACTS
MODIFIED

ORIGIN: EISP.
2/2/71 SGD. J.T.

REVISION: 2
3AR & 3AF
CONTACTS MODIFIED

ORIGIN: EISP.
26/2/71 SGD J.T.

REVISION: 1
87 CONTACT MOVED FROM
LINE 643 TO 644. N/C
CONTACT ADDED TO LINE 649
ALIVE INDICATORS WERE EAST
WEST, 1126, 1251, 1276 MODIFIED
ORIGIN: EISP.
9/2/71 SGD.

DATE 10.1.71

CHECKED BY

APPROVED BY

DATE

KEY DIAG. NO	
EXT. DIAG. NO	S
REL. DIAG NO	
PANEL LAYOUT M	

X 361U	
HTX 361U	

TX 30

010/4