



10736



28

10736

SCHEME FOR MCC 3B - SEAFORTH GRAIN TERMINAL.

DEWHURST & PARTNER LTD.
MELBOURNE WORKS. HOUNSLOW.

TITLE: SCHEME FOR MCC 3B SEAFORTH GRAIN TERMINAL

REVISION: 9
OVERSPEED
TIMER ADDED
ORIGIN: ICD
16/1/73 JS

REVISION: 8
TRIPPER OVERLOADS
REPLACED BY LRI
& HOL & LOL
ORIGIN: ICD
9/1/73 JS

REVISION: 7
INTERLOCKS FROM TRIP
MODIFIED ON LINES
552 & 553 05/72 NOW
N/O 80 RELAY R85
CONTACTS NOW N/C
ORIGIN: ICD
27/12/72 JS

REVISION: 6
TURNHEAD INTERLOCK CCT
ADDED TO OPEN CONTACTOR
ADDED TO CABLE RELAY
ORIGIN: ICD
18/7/72 JS

REVISION: 5
DESK TERMINALS
ADDED
ORIGIN: ICD
1/2/72 SCD JS

REVISION: 4
CHUTE BLOCK
& INDICATION WAS
TO TERM 76
ORIGIN: EISP
10/3/71 SGP JT

REVISION: 3
3AR & 3AF
& CBR3 CONTACTS
MODIFIED
ORIGIN: EISP
2/2/71 SGP JT

REVISION: 2
3AR & 3AF
CONTACTS MODIFIED
ORIGIN: EISP
26/2/71 SGP JT

REVISION: 1
REWORKED FROM
LINE 644 TO 644, N/C
CONTINUED DUE TO
VALVE INDICATORS WERE NOT
INSTALLED (SEE 10736)
ORIGIN: EISP
19/2/71 SGP

REVISION: 10
TRIPPER TROLLEY
RESET BUTTON
LINKED OUT
ORIGIN: ICD
29/1/73 JS

REVISION: 11
MODIFICATION TO TRIPPER
TROLLEY BOARD AND
TRIPPER AT STATION
ORIGIN: ICD
14/10/80 RJ

REVISION: 12
TRIPPER TROLLEY
BOARD AND
TRIPPER AT STATION
ORIGIN: ICD
29/1/73 JS

REVISION: 13
TRIPPER TROLLEY
BOARD AND
TRIPPER AT STATION
ORIGIN: ICD
29/1/73 JS

REVISION: 14
TRIPPER TROLLEY
BOARD AND
TRIPPER AT STATION
ORIGIN: ICD
29/1/73 JS

ISSUE	1	2	3	4	5	6	7	8	9	10	11	12
DTX 361U/4												
DTX 361U/4												

THE DESIGN AND MANUFACTURING INFORMATION CONTAINED IN THIS DRAWING IS THE EXCLUSIVE RIGHT OF DEWHURST & PARTNER LTD. AND MUST NOT BE COPIED OR USED FOR MANUFACTURING PURPOSES	KEY DIAG. NO.	EXT. DIAG. NO.	REL. DIAG. NO.	PANEL LAYOUT NO.
DTX 361U/4	STX 361U			HTX 361U