## Gas Leakage monitoring & Alerting system for Industries

## Assignment-1

## **CODE:**

```
void setup()
Serial.begin(9600);
pinMode(3,OUTPUT);
pinMode(2,INPUT);
void loop()
int motion=digitalRead(2);
Serial.print("Position is :");
Serial.println(motion);
double data=analogRead(A2);
double n = \frac{data}{1024};
double volt = n*5;
double off=volt-0.5;
double temp=off*100;
Serial.print("temp value :");
Serial.println(temp);
if(motion==1&&temp>=60)
{
tone(3,3);
}
else if(temp>=60)
{
tone(3,4);
```

```
}
else if(motion==1)
{
tone(3,5);
}
else
noTone(3);
Serial.print("temp value :");
Serial.println(temp);
if(motion==1&&temp>=60)
tone(3,3);
else if(temp>=60)
tone(3,4);
}
else if(motion==1)
tone(3,5);
}
else
{
noTone(3);
}
```

## **OUTPUT:**



