Assignment-4

Question:

Writecodeandconnections in wokwifor the ultrasonic sensor.

Wheneverthedistance is less than 100 cmssendan "alert" to the IBM cloud and display in the device recent events.

Code:

```
#definetrigPin12
#defineechoPin13
intBuzzer=8;//Connectbuzzerpinto8intledPin
=6;//ConnectLEdpinto6
intduration, distance;//tomeasurethedistanceandtimetaken
voidsetup(){
     Serial.begin(9600);
     //Definetheoutputandinputobjects(devices)pin
     Mode(trigPin,OUTPUT);pinMode(echoPin,
     INPUT);pinMode(Buzzer,
     OUTPUT);pinMode(ledPin,OUTPUT);
}
voidloop(){
  digitalWrite(trigPin,HIGH);delayMic
  roseconds(10);digitalWrite(trigPin,
  LOW);duration=pulseIn(echoPin,HI
  GH);distance=(duration/2)/29.1;
  // when distance is greater than or equal to 200 OR less than or equal to 0, the buzzer and LED are off
 if(distance>=200||distance<=0)
     Serial.println("noobjectdetected");digita
     IWrite(Buzzer,LOW);
```

Output:

