
ASSIGNMENT 4

INPUT:



CODE:

#include <stdio.h>

#include <stdbool.h>

#include <freertos/FreeRTOS.h>

#include <freertos/task.h>

#include <esp_err.h>

#include "ultrasonic.h"

#define ECHO_GPIO 12

#define TRIGGER_GPIO 13

```
#define MAX DISTANCE CM 500 // Maximum of 5 meters
void ultrasonic_test(void *pvParameters)
{
  float distance:
  ultrasonic_sensor_t sensor = {
    .trigger_pin = TRIGGER_GPIO,
    .echo_pin = ECHO_GPIO
  };
  ultrasonic init(&sensor);
  while (true) {
    esp_err_t res = ultrasonic_measure(&sensor,
MAX_DISTANCE_CM, &distance);
    if (res == ESP_OK) {
       printf("Distance: %0.04f m\n", distance);
    } // Print error
    else {
       printf("Error %d: ", res);
       switch (res) {
         case ESP_ERR_ULTRASONIC_PING:
           printf("Cannot ping (device is in invalid state)\n");
```

```
break;
        case ESP_ERR_ULTRASONIC_PING_TIMEOUT:
           printf("Ping timeout (no device found)\n");
           break;
        case ESP_ERR_ULTRASONIC_ECHO_TIMEOUT:
           printf("Echo timeout (i.e. distance too big)\n");
           break;
        default:
           printf("%s\n", esp_err_to_name(res));
       }
    vTaskDelay(pdMS_TO_TICKS(500));
  }
}
void app_main()
  xTaskCreate(ultrasonic_test, "ultrasonic_test",
configMINIMAL_STACK_SIZE * 3, NULL, 5, NULL);
}
```

OUTPUT:

