Gas Leakage monitoring & Alerting system for Industries


Assignment-1

Code:

```
void setup(){
Serial.begin(9600);
pinMode(2,INPUT);
pinMode(12,OUTPUT);
void loop(){
int motion_value=digitalRead(2);
Serial.print("Position = ");
Serial.println(motion_value);
double data_value=analogRead(A2);
double n = data_value/1024;
double volt = n*5;
double off=volt-0.5;
double temp_value=off*100;
Serial.print("temp = ");
Serial.println(temp_value);
if(motion_value==1 || temp_value>=50) {
tone(12,3);
}
else{
```

```
noTone(12);
}
```

Output:



Working of sensors:

