Gas Leakage Monitoring And Alerting System

Coding

```
#include <LiquidCrystal.h>
LiquidCrystal lcd(5,6,8,9,10,11);
int redled=3;
int greenled=2;
int buzzer=4;
int sensor= A0;
int sensorThresh=400;
void setup()
{
pinMode(redled,OUTPUT);
pinMode(greenled,OUTPUT);
pinMode(buzzer,OUTPUT);
pinMode(sensor,INPUT);
Serial.begin(9600);
lcd.begin(16,2);
}
void loop()
int analogValue= analogRead(sensor);
Serial.print(analogValue);
if(analogValue>sensorThresh)
```

{

```
digitalWrite(redled,HIGH);
digitalWrite(greenled,LOW);
tone(buzzer,1000,10000);
lcd.clear();
lcd.setCursor(0,1);
lcd.print("ALERT");
delay(1000);
lcd.clear();
lcd.setCursor(0,1);
lcd.print("EVACUATE");
delay(1000);
}
else
{
digitalWrite(greenled,HIGH);
digitalWrite(redled,LOW);
noTone(buzzer);
lcd.clear();
lcd.setCursor(0,0);
lcd.print("SAFE");
delay(1000);
lcd.clear();
lcd.setCursor(0,1);
lcd.print("ALL CLEAR");
delay(1000);
}
```