TEAM ID	PNT2022TMID50064
Project Name	Hazardous area monitoring for
	industrial plants powered by IOT

PROJECT DEVELOPMENT PHASEDELIVERY OF SPRINT-2

CODE:

```
#include <LiquidCrystal.h>
LiquidCrystal lcd(5,6,8,9,10,11);
int redled = 2;
int greenled = 3;
int buzzer = 4;
int sensor = A0;
int sensorThresh = 400;
void setup()
{
pinMode(redled, OUTPUT);
pinMode(greenled,OUTPUT);
pinMode(buzzer,OUTPUT);
pinMode(sensor,INPUT);
Serial.begin(9600);
lcd.begin(16,2);
}
void loop()
int analogValue = analogRead(sensor);
Serial.print(analogValue);
 if(analogValue>sensorThresh)
```

```
digitalWrite(redled,HIGH);
digitalWrite(greenled,LOW);
tone(buzzer,1000,10000);
lcd.clear(); lcd.setCursor(0,1);
lcd.print("ALERT");
delay(1000);
   lcd.clear();
   lcd.setCursor(0,1);
   lcd.print("EVACUATE");
   delay(1000);
  }
  else
  {
   digitalWrite(greenled,HIGH)
   ;digitalWrite(redled,LOW);
   noTone(buzzer);
   lcd.clear();
   lcd.setCursor(0,0);
   lcd.print("SAFE");
   delay(1000);
   lcd.clear();
   lcd.setCursor(0,1);
   lcd.print("ALL
   CLEAR");delay(1000);
  }
}
```