Harzardous Area Monitoring for Industrial Plant Powered by IOT

Assignment – II: **Topic**: PYTHON CODE TO GET TEMPERATURE AND HUMIDITY VALUE Name: Divesh.V **Register Number**: 920819106016 E-Mail Id: divesh16032002@gmail.com Code: Import random Import time Def CheckTemp(temperature): If temperature>70: Print("Temperature is high") Temp = random.randint(-40,100) Humid = random.randint(0,100) While True: Temp = random.randint(-40,100) Humid = random.randint(0,100) Print("Temperature = "+str(temp)) Print("Humidity = "+str(humid))

CheckTemp(temp)

Time.sleep(1)