PROJECT DEVELOPMENT PHASE SPRINT 4

```
#include <OneWire.h>
#include <DallasTemperature.h>
#define ONE_WIRE_BUS 5
OneWire oneWire(ONE_WIRE_BUS);
DallasTemperature sensors(&oneWire);
float Celcius=0;
float Fahrenheit=0;
float voltage=0;
const int analogInPin = A0;
int sensorValue = 0;
unsigned long int avgValue;
float b;
int buf[10],temp;
void setup(void)
{
Serial.begin(9600);
sensors.begin();
int sensorValue = analogRead(A1);
voltage = sensorValue * (5.0 / 1024.0);
}
void loop(void)
{
sensors.requestTemperatures();
Celcius=sensors.getTempCByIndex(0);
Fahrenheit=sensors.toFahrenheit(Celcius);
for(int i=0;i<10;i++)
{
buf[i]=analogRead(analogInPin);
delay(10);
```

```
}
for(int i=0;i<9;i++)
{
for(int j=i+1; j<10; j++)
{
if(buf[i]>buf[j])
{
temp=buf[i];
buf[i]=buf[j];
buf[j]=temp;
 }
 }
for(int i=2;i<8;i++)
avgValue+=buf[i];
float pHVol=(float)avgValue*5.0/1024/6;
float phValue = -5.70 * pHVol + 21.34;
Serial.println(phValue);
Serial.print("pH");
Serial.print(" C ");
Serial.print(Celcius);
Serial.print(voltage);
Serial.print("V");
delay(10000);
}
```



