ASSIGNMENT-4

Date	31October2022
Team ID	PNT2022TMID52223
Maximum Marks	2Marks

Question:


*Write code and connections in wokwi for the ultrasonic sensor.

*Write code and connections in work for ultrasonic sensor .Whenever distance is less than 100cms send "alert" to ibm cloud and display in device recent events.


Code:

```
#define ECHO PIN 2
#define TRIG_PIN 3
void setup() {
  Serial.begin(115200);
  pinMode(LED_BUILTIN, OUTPUT);
  pinMode(TRIG PIN, OUTPUT);
  pinMode(ECHO_PIN, INPUT);
float readDistanceCM() {
  digitalWrite(TRIG_PIN, LOW);
  delayMicroseconds(2);
  digitalWrite(TRIG_PIN, HIGH);
  delayMicroseconds(10);
  digitalWrite(TRIG_PIN, LOW);
  int duration = pulseIn(ECHO_PIN, HIGH);
  return duration * 0.034 / 2;
}
void loop() {
  float distance = readDistanceCM();
  bool isNearby = distance < 100;</pre>
  digitalWrite(LED_BUILTIN, isNearby);
  Serial.print("Measured distance: ");
  Serial.println(readDistanceCM());
  delay(100);
}
WOKWI LINK: https://wokwi.com/projects/347115384217797204
```

Solution:




Solution run:



OUTPUT:

DATA IS SENT TO IBM CLOUD WHEN OBJECT IS DETECTED



When no object is detected

