1.Write Code and connections in wokwi for ultrasonic sensor. whatever distance is less than 100 cms send "Alert" to ibm cloud aand display in device recent events.

```
Solution:
//Pins
const int TRIG_PIN = 7;
const int ECHO PIN = 8;
//Anything over 400 cm (23200 us pulse) is "out of range"
const unsigned int MAX_DIST = 23200;
void setup() {
// The Trigger pin will tell the sensor to range find
Pin Mode(TRIG_PIN, OUTPUT);
digital Write(TRIG PIN, LOW);
//Set Echo pin as input to measure the duration of
//pulses coming back from the distance sensor
pinMode(ECHO_PIN, INPUT);
// We'll use the serial monitor to view the sensor output
Serial.begin(9600);
}
void loop()
{ unsigned long
t1;
```

```
unsigned long t2;
unsigned long pulse_width;
float cm;
float inches;
// Hold the trigger pin high for at least 10 us
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG PIN, LOW);
// Wait for pulse on echo pin
while (digitalRead( ECHO_PIN )==0 );
// Measure how long the echo pin was held high (pulse width)
// Note: the micros() counter will overflow after-70 min
t1= micros ();
 while (digitalRead(ECHO_PIN) == 1);
 t2 = micros();
 pulse_width = t2-t1;
// Calculate distance in centimeters and inches. The constants
//are found in the datasheet, and calculated from the assumed speed
// of sound in air at sea level (- 340m/s)
cm=pulse_Width / 58;
inches = pulse_width/148.0;
```


```
// Print out results
if (pulse_width >MAX _
DIST ){Serial.println("Out of
range");
} else
Serial.print("The Measured Distance in cm: ");
Serial.println(cm);
if( cm < 100 ){
  //while(true){
   Serial.println("Alert!!");
   //}
}
Serial.print("*********************************);
}
//wait at least 1000ms before next measurement
Delay(1000);
}
```

Output:


1. If the distance is less than 100 cms, it alerts.

```
WOKWI B SAVE - SHARE
                                                                                                                                                                                             Docs (A
  hc-sr04.ino diagram.json ● Library Manager ▼
                                                                                                          Simulation
                                                                                                                                                                                       ₫00:00.466 (%58%
          const int TRIG_PIN = 7;
const int ECHO_PIN = 8;
          // Anything over 400 cm (23200 us pulse) is "out of range"
const unsigned int MAX_DIST = 23200;
                                                                                                                                                                     // The Trigger pin will tell the sensor to range find
pinWode(TRIG_PIN, OUTPUT);
digitalWrite(TRIG_PIN, LOW);
                                                                                                                                  Bannata (Mar -) ES
                                                                                                                                 OO UNO
            //Set Echo pin as input to measure the duration of
//pulses coming back from the distance sensor
pinMode(ECHO_PIN, IMPUT);
            // We'll use the serial monitor to view the sensor output
Serial.begin(9600);
                                                                                                                                      void loop() {
            unsigned long t1;
unsigned long t2;
unsigned long pulse_width;
float cm;
float inches;
                                                                                                      ***********
                                                                                                      The Measured Distance in cm : 84.14
                                                                                                      Alert!!
                                                                                                                                                                                            // Hold the trigger pin high for at least 10 us
```

2. If the distance is more than 100 cms, it won't alert



3. Simulation and code execution







IBM cloud output:

