ASSIGNMENT-4

Write code and connections in wokwi for the ultrasonic sensor. Whenever the distance is less than 100 cms send an "alert" to the IBM cloud and display in the device recent events. Upload document with wokwi share link and images of IBM cloud

CODE:

```
long int
echoPin=7;
long int
trigPin=5;
void setup()
 Serial.begin(96
 00);
 pinMode(7,OU
 TPUT);
 pinMode(5,INP
 UT);
void loop()
 int duration,
 distance;
 digitalWrite(3,L
 OW);
 delayMicroseco
 nds(2);
 digitalWrite(3,H
 IGH);
 delayMicroseco
 nds(10);
 digitalWrite(3,L
 OW);
 duration=pulseIn(7,H
 IGH);
 distance=(duration*0
 .034/2); delay(1000);
 if (distance<=100)
  Serial.println("ALERT!!");
```

OUTPUT:



