Assignment-4

Date	1 NOVEMBER 2022
Team ID	PNT2022TMID24462
Project Name	Smart Farmer – IOT Enabled Smart Farming Application
Maximum Marks	2 Marks

Question:

Write code and connections in wokwi for the ultrasonic sensor. Whenever the distance is less than 100 cms send an "alert" to the IBM cloud and display in the device recent events.

Wokwi link:

https://wokwi.com/projects/347938590387339858

Code:


```
const int TRIG_PIN = 7;
const int ECHO_PIN = 8;
//anything over 400cm(23200 us pulse)is "out of range"
const unsigned int MAX_DIST = 23200;
void setup() {
//The Trigger pin will tell the sensor to range find

pinMode(TRIG_PIN, OUTPUT);
digitalWrite(TRIG_PIN, LOW);
//Set Echo pin as input to measure the duration of pulse coming back from the
//distance sensor
pinMode(ECHO_PIN, INPUT);
```


```
//We'll use the serial monitor to view the sensor output
 Serial.begin(9600);
void loop() {
 unsigned long t1;
 unsigned long t2;
 unsigned long pulse width;
 float cm;
 float inches;
//Hold the trigger pin high for at least 10us
 digitalWrite(TRIG_PIN, HIGH);
 delayMicroseconds(10);
 digitalWrite(TRIG PIN, LOW);
//wait for pulse on echo pin
 while (digitalRead(ECHO_PIN) == 0);
//Measure how long the echo pin was held high (pulse width)
//note the micros()counter will overflow after -70min
 t1 = micros();
 while (digitalRead(ECHO PIN) == 1);
 t2 = micros();
 pulse width = t2 - t1;
//calculate distance in centimeters and inches. The constants are found in
//datasheet, and calculated from the assumed speed of sound in air at
sealevel(-340m/s)
 cm = pulse width / 58;
 inches = pulse width / 148.0;
//print out results
```

```
if (pulse_width > MAX_DIST) {
  Serial.println("Out of range");
 }
 else
{
  Serial.println("*******");
  Serial. println("The Measured Distance in cm:");
  Serial.println(cm);
  if (cm < 100)
  {
//while (true)
    Serial.println("Alert!");
   }
  }
  Serial.println("*******");
}
//wait at least 1000ms before next measurement
 delay(1000);
}
```

Case 1: If the Distance less than 100 cms it will Alert.



Case 2: If the Distance greater than 100 cms it wont Alert.



Case 3: If the distance is beyond the limit it will display Out Of Range.

```
sketch.ino diagram.json ● Library Manager ▼
                                                                                                                                                                                                                                                       Simulation
                   const int TRIG_PIN = 7;
const int ECHO_PIN = 8;
                                                                                                                                                                                                                                                                                                                                                                                                                                                         Ō00:12.471 ⊘99%
                                                                                                                                                                                                                                                     5 • •
                  COMS. IN EVOLUTE *8;

//amything over 400cm(23200 us pulse)is "out of range

const unsigned int MX_DIST = 23200;

wold setur() {

//The Trigger pin will tell the sensor to range find
                    pinMode(TRIG_PIN, OUTPUT);
digitalWrite(TRIG_PIN, LOW);
//set Echo pin as input to measu
                                                                                                                                                                                                                                                                                                                                 SE SETTION OR THE SET
               serial.begin(9600);
}

void loor() {
    unsigned long t1;
    unsigned long t2;
    unsigned long t2;
    unsigned long pulse_width;
    float cm;
    float inches;
    //NoId the trigger pin high for at least 10us
    digitalmrite(REIG PIN, HIGH);
    delayMicroseconds(10);
    digitalmrite(REIG PIN, LON);
    //Aut for pulse on echo pin
                                                                                                                                                                                                                                                                                                                                      AROUTHO UNO
                                                                                                                                                                                                                                                                                                                                              TOWER AMAION IN
                      ogitalmirie(100_PIN) (00);
//wait for pulse on echo pin
while (digitalRead(EGNO_PIN) == 0);
//wesure how long the echo pin was held high (pulse width)
//wote the micros()counter will overflow after -70min
t1 = micros();
while (digitalRead(EGNO_PIN) == 1);
t2 = micros();
pulse width = t2 - t1;
//acquiate distance in centimeters and inches. The constants
                                                                                                                                                                                                                                                    Out of range
                                                                                                                                                                                                                                                    Out of range
```

Circuit:

