

## Question:

Write code and conection in wokwi for ulsorsonic sensor .when ever distance lessthan 100 cms send alert "to ibm could and diplay in device recend events upload document with wokwi share link and image of ibm cloud

## Program:

```
#define eCHO_PIN 2
#define TRI6_PIN 3
void selup() (
 Serial begin (115200)
 pinMode(LED_BUILTIN_OUTPUT)
 pinPlode(TRIG_PIN_OUTPUT),
pinMode(ecHo_PIn_InPUT),
3
float readDistanceCM() (
 digitalWrite(TRIG_PIN_LOW),
 delayMicroseconds(2)
 digital@rite(TRIG_PIN_HIGH),
 delayMicroseconds(10)
 digitalWrite(TRI6_PIN_LOW),
 int duration = pulseln(ecHO_PIN_HIGH),
 return duration 0.034 / 2,
3
void loop() (
 float distance = readDistanceCM().
 bool isflearby = distance < 100,
 digital@rite(LEO_BUILTIN, ishearby),
 Serial print ("Measured distance "),
 Serial printin (read Distance CIP()),
```







## Link:

https://wokwi.com/projects/290056311044833800