


5 - S65 CALC NoWeld Line quality

Description

Check for "No Weld" out of the laser line.

Icon



Parameters





Parameter	Comment
Verbosity level	Selection of verbosity level. Larger verbosity levels offer more overlay information.

Threshold	Max. allowed laser line intensity for a "no weld" condition in the found seam area. [Greylevel]
Search height	Measurement area for "no weld" condition above and below the found laser line shape inside the found seam area. [Pixel]

■ Measured values for plotter

726	Bad Penetration Multi
-----	-----------------------

Subgraphs interface

IN bridges OUT bridges

 image	ROI penMulti	
☑ value	ROI grey valid	

■ Graph block diagram

