


5 - S66 CALC NoWeld Line LapJoint

Description

Check for "no weld" out of tracking the laser lines by LapJoint.

Icon



Parameters





Parameter	Comment	
Number	Max. allowed horizontal distance between the two found seam border positions for a "no weld" condition. [Pixel]	

Measured values for plotter

726	Bad Penetration Multi	

Subgraphs interface

IN bridges

OUT bridges

 image	ROI penMulti	
☑ value	ROI grey valid	

■ Graph block diagram

