

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
49	All work activities. Working in potential gaseous atmospheres.	Gas asphyxiation	Employees and other contractors	<ul> <li>Atmospheric testing to be completed before entering a confined space.</li> <li>Gas testers to check for methane, hydrogen sulphide and carbon monoxide.</li> <li>No lone working permitted.</li> <li>Ensure you have a valid 'Permit to Work' for all activities.</li> </ul>	Low