

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
57	All work activities Working in gaseous atmosphere with Respiratory Protective Equipment	Respiratory Protective Equipment Risk of asphyxiation from poisonous gases or suffocation owing to oxygen depleted environment.	Employees and other contractors	 All work areas and confined spaces to be checked for noxious, poisonous or oxygen depletion. All users of Respiratory Protective Equipment must be trained and assessed in its use. The mask must be appropriate for task. Sanitise the mask before use. Before use there must be a face fit test. Users must be clean shaven with maximum of 24 hours growth. Seal test must be carried out prior to every use. Physical examination of all parts for damage must be completed before every use. Mask must be compatible with all other Personal Protective Equipment being used e.g. hard hats, ear defenders, prescription glasses. 	Low