

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
51	All work activities	Hot Works  Burning, ignition of flammable materials	Employees and other contractors	<ul> <li>Hot Works Permit to be supplied for all grinding, cutting and heating activities.</li> <li>Area to be cordoned off and screen to prevent injury by flying particles.</li> <li>All gas cylinders and equipment to be tested transported and used as per risk assessments for flammable liquids.</li> <li>Dry powder fire extinguisher to be on site.</li> <li>Correct Personal Protective Equipment to be worn at all times (MTS minimum standards) including: face mask, gauntlets, hearing protection.</li> </ul>	