

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
36	All work activities	Weather Hot / cold / wet, Hypothermia, Heat stress, Localised flooding, High winds	Employees and other contractors	Hot Ensure Protection is used e.g. sun screen, neck shield, head protection, ample water supply, take rest breaks in shaded areas, and where possible – work in the shade. Cold Appropriate Personal Protective Equipment, keep warm, and avoid lone working. Consume plenty of warm fluids / food. Wet Wet weather clothing. Wind Be aware of high winds when working at height or in open / exposed areas. Flooding Assess area for access and egress in the event of rising water.	Low