UUT Report

Station ID: IT-W-7303101

Serial Number: NONE

Date: martedì 17 gennaio 2023

Time: 15:04:02 Operator: ITLAVIT1

Execution Time: 00:07:30.003

Number of Results: 476
UUT Result: Passed

Begin Sequence: MainSequence

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1120_Active.seq)

DUT recap	
Status:	Done
TestResults/Data:	
Serial Number:	L103AB101D
Type Designator:	M4M30SEA
FW Version:	P2.6.14.0
PMD-1120_Active	
Status:	Passed
Module Time:	450.189

Begin Sequence: PMD-1120_Active (C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1120_Active.seq)

Debug Init	
Status:	Skipped

Touch - Go Home	
Status:	Passed
Module Time:	20.4527

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch_GoConfigurationIO	
Status:	Passed

Module Time:	4.3398
Touch - Go Home	
Status:	Passed
Module Time:	20.3838

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go Home	
Status:	Passed
Module Time:	20.3854

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

INPUTS Set Tariff		
Status:	Passed	
Module Time:	0.162359	
Additional Results - Import Test	0.120200	
Status:	Done	
TestResults/Data:		
Import:	0.85	
Export:	0	
Import _ Pre Integration:	0	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Import Test		
Status:	Passed	
Pass/Fail COMM Export - Import Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ActiveImport Read		
Status:	Skipped	

Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	P P P P
Status:	Skipped
Additional Results - Export Test	
Status:	Done
TestResults/Data:	
Import:	0.85
Export:	0.85
Import _ Pre Integration:	0.85
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	rassa
Status:	Passed
Touch Reactivate	rabba
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	окіррей
Status:	Skipped
Pass/Fail HMI - Export Test	окіррей
Status:	Skipped
Touch - Go Home	окіррей
Status:	Skipped
INPUTS Set Tariff	отпрос
Status:	Passed
Module Time:	0.0533823
Additional Results - Import Test	0.0333023
Status:	Done
TestResults/Data:	Done
Import:	0.88
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	U
Status:	Passed
Pass/Fail COMM Export - Import Test	rasseu
Status:	Passed
Touch Reactivate	rasseu
	Clrinnad
Status: Touch - Go Home	Skipped
	Ckinned
Status:	Skipped
Touch ActiveImport Read Status:	Ckinned
	Skipped
Pass/Fail HMI - Import Test	Ckinged
Status:	Skipped
Touch Colleges	
Touch - Go Home Status:	Skipped

Additional Results - Export Test	
Status:	Done
TestResults/Data:	
Import:	0.88
Export:	0.89
Import _ Pre Integration:	0.88
Export _ Pre Integration:	0.00
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	l d33Cd
Status:	Passed
Touch Reactivate	i dosed
Status:	Skipped
Touch - Go Home	окіррец
Status:	Skipped
Touch ActiveExport Read	Экіррец
Status:	Skipped
Pass/Fail HMI - Export Test	Экіррей
Status:	Skipped
Touch - Go Home	Зкіррей
Status:	Skipped
INPUTS Set Tariff	Зкіррей
Status:	Passed
Module Time:	0.0403366
Additional Results - Import Test	0.0403300
Status:	Done
TestResults/Data:	Done
Import:	0.79
Export:	0.79
·	0
Import _ Pre Integration:	U
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Pass/Fail COMM Import - Import Test Status:	Passed
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test	Passed
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status:	
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate	Passed Passed
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status:	Passed
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home	Passed Passed Skipped
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status:	Passed Passed
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ActiveImport Read	Passed Passed Skipped Skipped
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ActiveImport Read Status:	Passed Passed Skipped
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ActiveImport Read Status: Pass/Fail HMI - Import Test	Passed Passed Skipped Skipped Skipped
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ActiveImport Read Status: Pass/Fail HMI - Import Test Status:	Passed Passed Skipped Skipped
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ActiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home	Passed Passed Skipped Skipped Skipped Skipped
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ActiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home Status:	Passed Passed Skipped Skipped Skipped
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ActiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home Status: Additional Results - Export Test	Passed Passed Skipped Skipped Skipped Skipped Skipped
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ActiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home Status: Additional Results - Export Test Status:	Passed Passed Skipped Skipped Skipped Skipped
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ActiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home	Passed Passed Skipped Skipped Skipped Skipped Done
Pass/Fail COMM Import - Import Test Status: Pass/Fail COMM Export - Import Test Status: Touch Reactivate Status: Touch - Go Home Status: Touch ActiveImport Read Status: Pass/Fail HMI - Import Test Status: Touch - Go Home Status: Status: Touch - Go Home Status: Touch - Status: Touch - Status: Touch - Status: Touch - Status: Status:	Passed Passed Skipped Skipped Skipped Skipped Skipped

Export:	0.88
Import _ Pre Integration:	0.79
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	rassea
Status:	Passed
Touch Reactivate	russeu
Status:	Skipped
Touch - Go Home	Бкіррец
Status:	Skipped
Touch ActiveExport Read	Экіррец
Status:	Skipped
	Skipped
Pass/Fail HMI - Export Test	Chiomad
Status:	Skipped
Touch - Go Home	Ckinned
Status: INPUTS Set Tariff	Skipped
	Dogg d
Status:	Passed
Module Time:	0.0512802
Additional Results - Import Test	15
Status:	Done
TestResults/Data:	
Import:	0.85
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
TestResults/Data:	
	0.85
Import:	
Import: Export:	0.86
Export:	0.86
Export: Import _ Pre Integration:	0.86 0.85

Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
INPUTS Set Tariff	
Status:	Passed
Module Time:	0.0373515
Additional Results - Import Test	
Status:	Done
TestResults/Data:	
Import:	0.82
Export:	0
·	
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	D
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
TestResults/Data:	
Import:	0.82
Export:	0.83
Import _ Pre Integration:	0.82
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	

Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
INPUTS Set Tariff	
Status:	Passed
Module Time:	0.0452256
Additional Results - Import Test	0.0.02200
Status:	Done
TestResults/Data:	200
Import:	0.86
Export:	0
Import _ Pre Integration:	0
	0
Export _ Pre Integration: Pass/Fail COMM Import - Import Test	U
Status:	Passed
Pass/Fail COMM Export - Import Test	rasseu
Status:	Passed
Touch Reactivate	Passeu
	Ckinned
Status: Touch - Go Home	Skipped
	Claimmand
Status:	Skipped
Touch ActiveImport Read	Climand
Status:	Skipped
Pass/Fail HMI - Import Test	CL:
Status:	Skipped
Touch - Go Home	a
Status:	Skipped
Additional Results - Export Test	
Status:	Done
TestResults/Data:	
Import:	0.86
Export:	0.87
Import _ Pre Integration:	0.86
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	

Status:	Skipped	
Pass/Fail HMI - Export Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	

Debug Dispose	
Status:	Skipped

End Sequence: PMD-1120_Active

End Sequence: MainSequence

End UUT Report