## **UUT Report**

Station ID: IT-W-7303101

Serial Number: NONE

Date: giovedì 1 giugno 2023

Time: 10:19:16
Operator: administrator

Execution Time: 350.9958941 seconds

Number of Results: 431 UUT Result: Passed

**Begin Sequence: MainSequence** 

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1120\_Active.seq)

DUT recap	
Status:	Done
Serial Number:	M086AB1000
Type Designator:	M4M30SEA
FW Version:	P3.0.0.4
PMD-1120_Active	
Status:	Passed
Module Time:	350.8357259

Begin Sequence: PMD-1120\_Active

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1120\_Active.seq)

Debug Init	
	Skipped

Touch - Go Home	
Status:	Passed
Module Time:	17.573617

**Begin Sequence: Touch\_GoHome** 

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Touch_GoConfigurationIO	
Status:	Passed
Module Time:	4.4123975

Touch - Go Home	
Status:	Passed
Module Time:	17.0397622

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Touch - Go Home	
Status:	Passed
Module Time:	16.827326

 $\label{lem:begin_sequence} Begin Sequence: Touch\_GoHome \\ (C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)$ 

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

INPUTS Set Tariff	
Status:	Passed
Module Time:	0.0671938

Additional Results - Import Test	
Status:	Done
Import:	0.05
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
Import:	0.05
Export:	0.05
Import _ Pre Integration:	0.05
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	

Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ActiveExport Read		
Status:	Skipped	
Pass/Fail HMI - Export Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
INPUTS Set Tariff		
Status:	Passed	
Module Time:	0.0901276	
Additional Results - Import Test		
Status:	Done	
Transport		

Additional Results - Import Test	
Status:	Done
Import:	0.06
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	,
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	The state of the s
Status:	Skipped
Additional Results - Export Test	The Residence of the State of t
Status:	Done
	0.06
Import:	0.05
Export:  Import _ Pre Integration:	0.06
Export _ Pre Integration:	0
	lo la
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	
TOUGH ACTIVE EXPORT REGIO	

Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
INPUTS Set Tariff	
Status:	Passed
Module Time:	0.0760692

Module Time:	0.0760692
Additional Results - Import Test	
Status:	Done
Import:	0.05
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
	Ji dosed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	The state of the s
Status:	Skipped
	Ovibbed
Pass/Fail HMI - Import Test	1
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
Import:	0.05
Export:	0.06
Import _ Pre Integration:	0.05
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
	rasseu
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	
Status:	Skipped
	<u>                                     </u>
Pass/Fail HMI - Export Test	Chinned
Status:	Skipped
Touch - Go Home	
Status:	Skipped
INPUTS Set Tariff	

Status:	Passed
Module Time:	0.0747917

Additional Results - Import Test	
Status:	Done
Import:	0.05
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	T. P.P. T.
	Skipped
	Скіррей
Touch - Go Home	Skipped
Status:	<u> Бкірреа</u>
Additional Results - Export Test	
Status:	Done
Import:	0.05
Export:	0.05
Import _ Pre Integration:  Export _ Pre Integration:	0.05 0
Pass/Fail COMM Import - Export Test	
	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
	Skipped
INPUTS Set Tariff	Paggod
Status:  Module Time:	Passed 0.0555771
inodule fillie.	0.0333//1

Additional Results - Import Test	
Status:	Done
Import:	0.06
Export:	0

Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
Import:	0.06
Export:	0.05
Import _ Pre Integration:	0.06
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	Bassad
Status:	Passed
Pass/Fail COMM Export - Export Test	Bassad
Status:	Passed
Touch Reactivate	Skipped
Status:	<del>Sкірре</del> й
Touch - Go Home Status:	Skipped
	Зкіррец
Touch ActiveExport Read  Status:	Skipped
	Зкіррец
Pass/Fail HMI - Export Test	Ckinned
Status:	Skipped
Touch - Go Home	Skinned
Status:	Skipped
INPUTS Set Tariff	Pageod
Status:  Module Time:	0.0501339
roduc fille.	JO.0301333
Additional Results - Import Test	

Status:	Done
Import:	0.05
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed

Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
Import:	0.05
Export:	0.05
Import _ Pre Integration:	0.05
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped

## Debug Dispose Status: Skipped

End Sequence: PMD-1120\_Active

**End Sequence: MainSequence** 

## **End UUT Report**