UUT Report

Station ID: IT-W-7303101

Serial Number: NONE

Date: mercoledì 29 marzo 2023

Time: 16:10:35 Operator: ITLAVIT1

Execution Time: 00:06:35.011

Number of Results: 506
UUT Result: Passed

Begin Sequence: MainSequence

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1120_Reactive.seq)

DUT recap		
Status:	Done	
TestResults/Data:		
Serial Number:	Q032AB102T	
Type Designator:	M4M30SMA	
FW Version:	P3.0.0.3	
PMD-1120_Reactive		
Status:	Passed	
Module Time:	395.024	

Begin Sequence: PMD-1120_Reactive

(C:\Users\itlavit1\OneDrive - ABB\LabRnD_Shared\TestStand\Sequences\M4M\PMD-1120_Reactive.seq)

Debug Init	
Status:	Skipped

Touch - Go Home	
Status:	Passed
Module Time:	16.1805

Begin Sequence: Touch_GoHome (C:\Users\itlavit1\OneDrive -

ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch_GoConfigurationIO	
Status:	Passed

Module Time:	4.33135
Touch - Go Home	
Status:	Passed
Module Time:	16.2982

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached		
Status:	Passed	

End Sequence: Touch_GoHome

Touch_GoConfigurationIO		
Status:	Passed	
Module Time:	4.35419	
Touch - Go Home		
Status:	Passed	
Module Time:	16.5188	

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

End Sequence: Touch_GoHome

Touch - Go Home	
Status:	Passed
Module Time:	16.3597

Begin Sequence: Touch_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached		
Status:	Passed	

End Sequence: Touch_GoHome

INPUTS Set Tariff	
Status:	Passed
Module Time:	0.0832335

Additional Results - Import Test		
Status:	Done	
TestResults/Data:		
Import:	0.07	
Export:	0	
Import _ Pre Integration:	0	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Import Test		
Status:	Passed	
Pass/Fail COMM Export - Import Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ReactiveImport Read		
Status:	Skipped	
Pass/Fail HMI - Import Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Additional Results - Export Test		
Status:	Done	
TestResults/Data:		
Import:	0.07	
Export:	0.08	
Import _ Pre Integration:	0.07	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Export Test		
Status:	Passed	
Pass/Fail COMM Export - Export Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ReactiveExport Read		
Status:	Skipped	
Pass/Fail HMI - Export Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
INPUTS Set Tariff		
Status:	Passed	
Module Time:	0.10404	
Additional Results - Import Test		
Status:	Done	
TestResults/Data:		
Import:	0.07	

Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	U
Status:	Passed
Pass/Fail COMM Export - Import Test	rasseu
Status:	Passed
Touch Reactivate	rasseu
Status:	Skipped
Touch - Go Home	Skipped
Status:	Skipped
Touch ReactiveImport Read	Skipped
Status:	Skipped
Pass/Fail HMI - Import Test	Skipped
Status:	Skipped
Touch - Go Home	Skipped
Status:	Skipped
Additional Results - Export Test	Зкіррец
Status:	Done
TestResults/Data:	Done
	0.07
Import:	0.07
Export:	
Import _ Pre Integration:	0.07
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	Description
Status:	Passed
Touch Reactivate	Claimpod
Status:	Skipped
Touch - Go Home	Claiman
Status:	Skipped
Touch ReactiveExport Read	Chimpad
Status:	Skipped
Pass/Fail HMI - Export Test	Claimpod
Status:	Skipped
Touch - Go Home	Ckinnad
Status:	Skipped
INPUTS Set Tariff Status:	Passed
Status:	
Module Time:	0.0779468
Additional Results - Import Test	Dane
Status:	Done
TestResults/Data:	0.00
Import:	0.08
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	

Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
TestResults/Data:	
Import:	0.08
Export:	0.08
Import _ Pre Integration:	0.08
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
INPUTS Set Tariff	- Chippen
Status:	Passed
Module Time:	0.0618969
Additional Results - Import Test	0.0010303
Status:	Done
TestResults/Data:	Done
Import:	0.07
Export:	0.07
	0
Import _ Pre Integration:	0
Export _ Pre Integration:	U
Pass/Fail COMM Import - Import Test	Dagged
Status:	Passed
Pass/Fail COMM Export - Import Test	De ser d
Status:	Passed
Touch Reactivate	

Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	o in prod
Status:	Skipped
Additional Results - Export Test	Строс
Status:	Done
TestResults/Data:	Done
Import:	0.07
·	0.07
Export:	
Import _ Pre Integration:	0.07
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
INPUTS Set Tariff	
Status:	Passed
Module Time:	0.0665845
Additional Results - Import Test	
Status:	Done
TestResults/Data:	
Import:	0.08
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	U
Status:	Passed
	rasseu
Pass/Fail COMM Export - Import Test Status:	Dagged
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveImport Read	
I	

Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
TestResults/Data:	·
Import:	0.08
Export:	0.09
Import _ Pre Integration:	0.08
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	<u>Skipped</u>
INPUTS Set Tariff	
Status:	Passed
Module Time:	0.117608
Additional Results - Import Test	
Status:	Done
TestResults/Data:	
Import:	0.08
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	

Status:	Skipped	
Additional Results - Export Test		
Status:	Done	
TestResults/Data:		
Import:	0.08	
Export:	0.08	
Import _ Pre Integration:	0.08	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Export Test		
Status:	Passed	
Pass/Fail COMM Export - Export Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ReactiveExport Read		
Status:	Skipped	
Pass/Fail HMI - Export Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	

Debug Dispose	
Status:	Skipped

End Sequence: PMD-1120_Reactive

End Sequence: MainSequence

End UUT Report