## **UUT Report**

**Station ID: IT-W-7303101** 

Serial Number: NONE

Date: mercoledì 29 marzo 2023

Time: 15:59:03 Operator: ITLAVIT1

**Execution Time:** 00:07:29.001

Number of Results: 533 UUT Result: Passed

**Begin Sequence: MainSequence** 

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1120\_Active.seq)

DUT recap		
Status:	Done	
TestResults/Data:		
Serial Number:	Q032AB102T	
Type Designator:	M4M30SMA	
FW Version:	P3.0.0.3	
PMD-1120_Active		
Status:	Passed	
Module Time:	449.57	

Begin Sequence: PMD-1120\_Active (C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1120\_Active.seq)

Debug Init	
Status:	Skipped

Touch - Go Home	
Status:	Passed
Module Time:	16.237

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Touch_GoConfigurationIO	
Status:	Passed

Module Time:	4.33642
Touch - Go Home	
Status:	Passed
Module Time:	16.328

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached		
Status:	Passed	

**End Sequence: Touch\_GoHome** 

Touch_GoConfigurationIO		
Status:	Passed	
Module Time:	4.34896	
Touch - Go Home		
Status:	Passed	
Module Time:	16.1511	

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Touch - Go Home	
Status:	Passed
Module Time:	16.3335

Begin Sequence: Touch\_GoHome
(C:\Users\itlavit1\OneDrive ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

INPUTS Set Tariff	
Status:	Passed
Module Time:	0.198262

Additional Results - Import Test		
Status:	Done	
TestResults/Data:		
Import:	0.07	
Export:	0	
Import _ Pre Integration:	0	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Import Test		
Status:	Passed	
Pass/Fail COMM Export - Import Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ActiveImport Read		
Status:	Skipped	
Pass/Fail HMI - Import Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Additional Results - Export Test		
Status:	Done	
TestResults/Data:		
Import:	0.07	
Export:	0.09	
Import _ Pre Integration:	0.07	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Export Test		
Status:	Passed	
Pass/Fail COMM Export - Export Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ActiveExport Read		
Status:	Skipped	
Pass/Fail HMI - Export Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
INPUTS Set Tariff		
Status:	Passed	
Module Time:	0.094671	
Additional Results - Import Test		
Status:	Done	
TestResults/Data:		
Import:	0.08	

Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
TestResults/Data:	
Import:	0.08
Export:	0.08
Import _ Pre Integration:	0.08
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
INPUTS Set Tariff	
Status:	Passed
Module Time:	0.0663799
Additional Results - Import Test	1
Status:	Done
TestResults/Data:	1
Import:	0.07
Export:	0
Import _ Pre Integration:	0
import _ i ic integration.	
Export _ Pre Integration:	0

Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	Строс
Status:	Skipped
Touch ActiveImport Read	отррес
Status:	Skipped
Pass/Fail HMI - Import Test	Экіррей
Status:	Skipped
Touch - Go Home	Зкіррец
	Climan
Status:	Skipped
Additional Results - Export Test	
Status:	Done
TestResults/Data:	
Import:	0.07
Export:	0.09
Import _ Pre Integration:	0.07
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	отррес
Status:	Skipped
INPUTS Set Tariff	Экірреа
Status:	Passed
Module Time:	0.0686632
Additional Results - Import Test	Description
Status:	Done
TestResults/Data:	
Import:	0.08
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	

Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
TestResults/Data:	
Import:	0.08
Export:	0.08
Import _ Pre Integration:	0.08
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
INPUTS Set Tariff	
Status:	Passed
Module Time:	0.0843617
Additional Results - Import Test	
Status:	Done
TestResults/Data:	
Import:	0.07
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	

Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
TestResults/Data:	
Import:	0.07
Export:	0.09
Import _ Pre Integration:	0.07
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveExport Read	
Status:	<u>Skipped</u>
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
INPUTS Set Tariff	
Status:	Passed
Module Time:	0.117267
Additional Results - Import Test	
Status:	Done
TestResults/Data:	
Import:	0.08
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ActiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	at :
Status:	Skipped
Touch - Go Home	
I	II .

Status:	Skipped	
Additional Results - Export Test		
Status:	Done	
TestResults/Data:		
Import:	0.08	
Export:	0.08	
Import _ Pre Integration:	0.08	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Export Test		
Status:	Passed	
Pass/Fail COMM Export - Export Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ActiveExport Read		
Status:	Skipped	
Pass/Fail HMI - Export Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	

Debug Dispose	
Status:	Skipped

End Sequence: PMD-1120\_Active

**End Sequence: MainSequence** 

## **End UUT Report**