## **UUT Report**

Station ID: IT-W-7303101

Serial Number: NONE

Date: giovedì 1 giugno 2023

Time: 10:33:56
Operator: administrator

Execution Time: 290.7113772 seconds

Number of Results: 455 UUT Result: Failed

**Failure Chain:** 

Step	Sequence	Sequence File
Pass/Fail COMM Import - Export Test	PMD-1120_Reactive	PMD-1120_Reactive.seq
PMD-1120_Reactive	MainSequence	PMD-1120_Reactive.seq

**Begin Sequence: MainSequence** 

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1120\_Reactive.seq)

DUT recap		
Status:	Done	
Serial Number:	M086AB1000	
Type Designator:	M4M30SEA	
FW Version:	P3.0.0.4	
PMD-1120_Reactive		
Status:	Failed	
Module Time:	287.9062077	

Begin Sequence: PMD-1120\_Reactive

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\PMD-1120\_Reactive.seq)

Debug Init		
Status:	Skipped	

Touch - Go Home	
Status:	Passed
Module Time:	16.8595683

**Begin Sequence: Touch\_GoHome** 

(C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

**End Sequence: Touch\_GoHome** 

Touch_GoConfigurationIO	
Status:	Passed
Module Time:	4.3760413

Touch - Go Home		

Status:	Passed
Module Time:	16.9800648

Begin Sequence: Touch\_GoHome (C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

### **End Sequence: Touch\_GoHome**

Touch - Go Home	
Status:	Passed
Module Time:	16.6337894

Begin Sequence: Touch\_GoHome (C:\Users\itlavit1\OneDrive - ABB\LabRnD\_Shared\TestStand\Sequences\M4M\CommonUtilitySequences.seq)

Pass/Fail - Home Reached	
Status:	Passed

## **End Sequence: Touch\_GoHome**

INPUTS Set Tariff	
Status:	Passed
Module Time:	0.0599013

Additional Results - Import Test		
Status:	Done	
Import:	0.05	
Export:	0	
Import _ Pre Integration:	0	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Import Test		
Status:	Passed	
Pass/Fail COMM Export - Import Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ReactiveImport Read		
Status:	Skipped	
Pass/Fail HMI - Import Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Additional Results - Export Test		
Status:	Done	
Import:	0.05	

Export:	0.05	
Import _ Pre Integration:	0.05	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Export Test		
Status:	Passed	
Pass/Fail COMM Export - Export Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ReactiveExport Read		
Status:	Skipped	
Pass/Fail HMI - Export Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
INPUTS Set Tariff		
Status:	Passed	
Module Time:	0.0665874	

Additional Results - Import Test	
Status:	Done
Import:	0.05
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
Import:	0.05
Export:	0.06
Import _ Pre Integration:	0.05
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	

Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ReactiveExport Read		
Status:	Skipped	
Pass/Fail HMI - Export Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
INPUTS Set Tariff		
Status:	Passed	
Module Time:	0.0885997	
Additional Results - Import Test		
Status:	Done	

Additional Results - Import Test		
Status:	Done	
Import:	0.04	
Export:	0	
Import _ Pre Integration:	0	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Import Test		
Status:	Passed	
Pass/Fail COMM Export - Import Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ReactiveImport Read		
Status:	Skipped	
Pass/Fail HMI - Import Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Additional Results - Export Test		
Status:	Done	
Import:	0.06	
Export:	0.05	
Import _ Pre Integration:	0.04	
Export _ Pre Integration:	0	
Pass/Fail COMM Import - Export Test		
Status:	Failed	
Pass/Fail COMM Export - Export Test		
Status:	Passed	
Touch Reactivate		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
Touch ReactiveExport Read		

Status:	Skipped	
Pass/Fail HMI - Export Test		
Status:	Skipped	
Touch - Go Home		
Status:	Skipped	
INPUTS Set Tariff		
Status:	Passed	
Module Time:	0.1098496	

Module Time:	0.1098496
Additional Results - Import Test	
Status:	Done
Import:	0.05
Export:	0
Import _ Pre Integration:	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	Passad
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveImport Read	
Status:	Skipped
	- Inches
Pass/Fail HMI - Import Test	China
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
Import:	0.05
Export:	0.05
Import _ Pre Integration:	0.05
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	,
Status:	Passed
	i assea
Touch Reactivate	la.
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveExport Read	
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
	Экіррец
Touch - Go Home	
Status:	Skipped
INPUTS Set Tariff	
Ir	

Status:	Passed
Module Time:	0.0478726

Additional Results - Import Test	
	Done
	0.06
<u>'</u>	0
	0
Export _ Pre Integration:	0
Pass/Fail COMM Import - Import Test	
Status:	Passed
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveImport Read	
	Skipped
Pass/Fail HMI - Import Test	
	Skipped
	<u> Бкіррей</u>
Touch - Go Home	Skipped
Status:	<u> Бкірреа</u>
Additional Results - Export Test	
	Done
· .	0.06
·	0.04
	0.06
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveExport Read	
	Skipped
Pass/Fail HMI - Export Test	
	Skipped
Touch - Go Home	
	Skipped
INPUTS Set Tariff	
	Passed
	0.0847899

Additional Results - Import Test	
Status:	Done
Import:	0.05
Export:	0

Import _ Pre Integration:	0
Export _ Pre Integration:	
Pass/Fail COMM Import - Import Test Status:	Passed
	rasseu
Pass/Fail COMM Export - Import Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Touch ReactiveImport Read	
Status:	Skipped
Pass/Fail HMI - Import Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped
Additional Results - Export Test	
Status:	Done
Import:	0.05
Export:	0.06
Import _ Pre Integration:	0.05
Export _ Pre Integration:	0
Pass/Fail COMM Import - Export Test	
Status:	Passed
Pass/Fail COMM Export - Export Test	
Status:	Passed
Touch Reactivate	
Status:	Skipped
Touch - Go Home	ompos.
Status:	Skipped
	Pubben
Touch ReactiveExport Read	Ckinned
Status:	Skipped
Pass/Fail HMI - Export Test	
Status:	Skipped
Touch - Go Home	
Status:	Skipped

Debug Dispose	
Status:	Skipped

End Sequence: PMD-1120\_Reactive

**End Sequence: MainSequence** 

# **End UUT Report**