BioEntryTM Firmware Revision Notes

Version 1.7



Revision Notes

Firmware Version 1.7

Build Number*

2007-5-4

- The updates in V1.7 firmware of SFM3500 series are incorporated.
- The following bug is fixed.
 - **BioEntry Smart FC** When Operation Mode is set to 1:N or Both, BioEntry beeps once after power-on.

*07020500	BioEntry Pass TC and BioEntry Smart TC
07021400	BioEntry Pass FC, BioEntry Pass OP, and BioEntry Smart OP
07041900	BioEntry Smart FC

Firmware Version 1.6

Build Number 06040400

2006-4-18

- The updates in V1.6 firmware of SFM3500 series are incorporated.
- In Normal mode, 1:N matching algorithm gets much faster without any performance degradation. The new algorithm is about two times faster than older versions. Since new Normal mode is faster than old Fast mode 1 for FC, fast mode setting is adjusted accordingly. New Fast mode 1 is equivalent to old Fast mode 2, new Fast mode 2 to old Fast mode 3, and so on. The Fast modes for OP and TC models haven't been changed.
- Time Schedule and Access Group are added.
- The default security level is changed to Auto Normal from 1/100,000.
- **BioEntry Smart** The minimum security level of a user is lowered to 1/1,000.
- BioEntry Pass OP and BioEntry Smart OP By tuning the sensor driver, the authentication performance is enhanced especially for dry fingers.

© 2006 by Suprema Inc.

1

Firmware Version 1.5 Build Number 05111100

2005-11-11

- The updates in V1.5 firmware of SFM3500 series are incorporated.
- ABA Track II output is supported.
- The following bugs are fixed.
 - The status LED is turned off after handling commands from GPIO inputs.
 - The status LED does not show the results of enroll/identify/verify commands properly if these commands are from serial interface.
 - In processing Write Configuration command cards, the module hangs if an invalid card is detected.

Firmware Version 1.4.4 Build Number 05100500

2005-10-05

• **BioEntry Pass TC and BioEntry Smart TC** The sensor driver is updated to enhance the ESD characteristics of the reader.

Firmware Version 1.4.3 Build Number 05090700

2005-09-07

- The sensor drivers and bootloader are updated to accommodate the changes in the SFM3500 series modules.
- BioEntry Pass OP The sensor driver is updated to enhance the EMI characteristics
 of the reader.

Firmware Version 1.4.2 Build Number 05083000

2005-08-30

• **BioEntry Pass OP** The Sensor driver and bootloader are updated to accommodate the changes in the SFM3520 module.

Firmware Version 1.4.1 Bui

Build Number 05081800

2005-08-18

© 2006 by Suprema Inc.

• Created.