

INDUSTRIAL INSPECTION REPORT

Equipment: Pump P-102

Inspection Date: 10 September 2026

Location: Production Unit A

Inspector: Maintenance Team

Finding:

Oil leakage was observed near the pump seal.

The mechanical seal shows visible signs of wear.

Recommendation:

Replace the damaged mechanical seal.

Perform a complete leak test after replacement.

Priority: High

Approval Required:

Approval is required for immediate maintenance.