



Utility Corridor Advisory

South Loop temporary pedestrian diversion

RECORD	STATUS	ACCESS	REVISION
45-0730-UC	ACTIVE	PUBLIC	07.30.45

A pressure-control component beneath the east sidewalk has been isolated after visible vapor and intermittent signal disruption. No evacuation order is active.

PUBLISHED EVENT LOG

- 22:51 ● First public report of visible vapor received.
- 23:06 ● Intermittent local signal disruption confirmed.
- 23:33 ● Pressure-control component isolated by repair crew.
- 23:47 ● Air reading returned to published neighborhood baseline.

CURRENT PUBLIC DIRECTION

- ☐ Use the marked west-side crossing and remain outside contractor barriers.
- ☐ Report persistent odor, vapor outside the marked area, or medical symptoms.
- ☐ Water, power, and transit remain available under temporary controls.