


Complete Flow (step-by-step)

1. **Start Test** — Press push button / send pc command
2. **Configure & Run Workload** — Select test,set target,execute on RISC-V core
3. **Inject Fault** — Fault engine flips bits in selected location
4. **ECC Check** — Correct(1-bit) or detect (2+ bits)erro
5. **Recover/Continue** — Restore checkpoint or halt safely if needed
6. **Monitor Power** — Check current/voltage. Trigger isolation if required(optional)
7. **Report to PC** — Send logs,status,metrics via UART