



ESQUEMA TIRO CARGA POR BAJA FRECUENCIA					
		PASO 1 (59.3 HZ)		PASO 3 (59.1 HZ)	
CIRCUITO	ESTADO ACTUAL	DEMANDA ACTUAL	PR-81	GRAFICA	PR-81
CHG 4020		0.00 f	NORMAL		
CIP 42030			NORMAL		
IGU 5125	f				
LAT 4110					
TAN 4030			NORMAL		
TIE 4040			NORMAL		
TXO 5115			NORMAL		
VEN 4060	m	400.00 f			
ARC 4010			NORMAL		
ARC 4040			NORMAL		
HEL 5030	o		NORMAL		
<hr/>					
PASO 2 (59.2 HZ)					
CIRCUITO	ESTADO ACTUAL	DEMANDA ACTUAL	PR-81	GRAFICA	
CHG 4010		-0.00 f	NORMAL		
IGU 5235	f				
LOC 4010	f		NORMAL		
LOC 4020	f				
LOC 4030	f				
LOC 4040	f				
LOC 4050	f				
OMT 4030			NORMAL		
REN 4050			NORMAL		
TPL 4010	o				
VEN 4050	m	400.00 f			
XCH 4010					
XCH 4020					
XCH 4030					
XCH 4040					
CAZ 4240	o		NORMAL		
CGN 4010	o	0.00 f			
CGN 4030		0.00 f			
PPN 4040					
TAN 4060			NORMAL		
TCA 4020					
TCA 4030					
TPL 4020					
TXO 5125			NORMAL		
<hr/>					
PASO 3 (59.1 HZ)					
CIRCUITO	ESTADO ACTUAL	DEMANDA ACTUAL	PR-81	GRAFICA	
JJT 4010					
JJT 4020					
JJT 4030					
JJT 4040					
JJT 4050					
JJT 4060					
JJT 4080					
<hr/>					
PASO 4 (58.9 HZ)					
GAR 4030					
MRA 4010					
MRA 4020					
MRA 4030					
REN 4010					
REN 4070					
TAN 4040					
OMT 4020					
<hr/>					
PASO 5 (58.7 HZ)					
GAR 4010					
PPN 4030					
PUM 4040					
PUM 4050					
REN 4020					
REN 4040					
<hr/>					
PASO 6 (58.5 HZ)					
CYC 4010	i				
CYC 4020					
CYC 4030					
JRN 4010					
JRN 4020					
JRN 4030					
JRN 4040					
JRN 4050					
TPL 4060					
CUS 4010	f				
LOC 4060	f				
PUM 4060					
LTP 4155					
TCA 4010					
TEZ 5010					
TEZ 5050					
TLZ 4020					
TLZ 4040					