

INCIDENT REPORT

Document Ref: INC-2024-07 | Equipment Failure / Unplanned Downtime

Incident Date	22 Jul 2024
Asset	Pump P-204 (Boiler Feed Water)
Event	Catastrophic DE bearing seizure
Downtime	38 hours unplanned
Reported By	Shift Engineer, Unit 2
Severity	High - production loss, no injury

Event Description

Pump P-204 drive-end bearing seized during normal operation at 14:20. Pump tripped on high vibration. Inspection confirmed complete failure of the DE bearing (SKF 6316) with secondary shaft scoring. Boiler feed water supply switched to standby pump P-205. Unit 2 load reduced for 38 hours during repair.

Preliminary Cause

Bearing failure due to progressive wear that was detected but not corrected in time. Root cause analysis to reference inspection and maintenance history for P-204.

Cross-References

This incident should be reviewed against the maintenance and inspection history of P-204. Relevant records exist in the plant document systems but were not consolidated prior to failure.