# MAINTENANCE TECHNICAL SUPPORT CENTER HEADQUARTERS MAINTENANCE OPERATIONS UNITED STATES POSTAL SERVICE



# Maintenance Management Order

**SUBJECT:** Remote Image Processing System

(RIPS\_AA) Preventive Maintenance

**TO:** All Maintenance Capable Sites

**DATE:** May 6, 2021

**PUB NO:** MMO-090-20

FILE CODE: K6

**FILE ID:** mm20089

**REV LEVEL**: af

This Maintenance Management Order (MMO) provides Operational and Preventive Maintenance Guidelines for the Remote Image Processing System (RIPS) (plant, hardware). This bulletin applies to Acronym RIPS and Class Code AA.

The minimum maintenance skill level required to perform each task is included in the Minimum Skill Level column of each checklist. This does not preclude higher level employees from performing any of this work.

## WARNING

Various products requiring Safety Data Sheets (SDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current SDS for each product used is on file and available to all employees. When reordering such a product, it is suggested that current SDS be requested. Refer to SDS for appropriate personal protective equipment.

### WARNING

The use of compressed or blown air is prohibited. An alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp rag, lint-free cloth, or brush must be used in place of compressed or blown air.

## WARNING

Steps contained in this bulletin may require the use of Electrical Work Plan (EWP) Personal Protective Equipment (PPE). Refer to the current EWP MMO for appropriate EWP PPE and barricade requirements.

Web Access: https://www1.mtsc.usps.gov

For questions or comments concerning this bulletin contact the MTSC HelpDesk, either online at MTSC>HELPDESK>Create/Update Tickets or call (800) 366-4123.

Frederick L. Jackson III

Manager

Maintenance Technical Support Center

**HQ** Maintenance Operations

- 1. Summary of Workload Estimate For RIPS System
- 2. RIPS Master Checklist 03-RIPS-AA-001-M Preventive Maintenance (PM)
- 3. RIPS Master Checklist 09-RIPS-AA-001-M Operational Maintenance (OM)

### **ATTACHMENT 1**

### **SUMMARY WORKLOAD ESTIMATE**

### **FOR RIPS**

#### **SUMMARY WORK LOAD ESTIMATES FOR RIPS**

Number of mailpieces Processed for 1 Year >

High end estim	nate					Operational Maintenance + Total Servicing				
						I	olai Servicii	ig		
	Routine	Repair	Routine	Non-	Total					
	Servicing	Time	Servicing	Productive	Servicing					
	per	per	+ Repair	Time per	per	1 Tour	2 Tours	3 Tours		
Operation	Machine	Machine	Time	Machine	Machine	Hrs/Yr	Hrs/Yr	Hrs/Yr		
Days	(Hrs/Yr)	(Hrs/Yr)*	(Hrs/Yr)	(Hrs/Yr) **	(Hrs/Yr)	OpM x 1	OpM x 2	OpM x 3		
5 Days	2.20	0.66	2.86	0.29	3.15	72.48	72.48	72.48		
6 Days	2.20	0.66	2.86	0.29	3.15	86.35	86.35	86.35		
7 Days	2.20	0.66	2.86	0.29	3.15	100.21	100.21	100.21		

<sup>\*</sup> Repair maintenance estimates based on 30% of preventive maintenance.

\*\* Based on 10% of total PM and repair.

THRESHOLDS and Hrs P	PM TIME SU ER Year	OPERATIONAL MAINTENANCE							
Daily (7 Day)	0.00		16 MI	16 MIN. PER DAY PER MACHINE					
			One	Two	Three				
Weekly	0.00		Tour	Tours	Tours				
Monthly	2.20	5 Day	69.33	69.33	69.33				
Quarterly	0.00	6 Day	83.20	83.20	83.20				
Semi-Annual	0.00	7 Day	97.07	97.07	97.07				

### NOTES:

<sup>\*</sup>Repair estimates based on 30% of servicing.

<sup>\*\*</sup>Based on 10% of total servicing and repair.

# THIS PAGE BLANK

# **ATTACHMENT 2**

### **RIPS MASTER CHECKLIST**

### 03-RIPS-AA-001-M

# PREVENTIVE MAINTENANCE (PM)

Time Total: (11) minutes

U.S. Postal Service		IDENTIFICATION														
Maintenance Checklist	WORK CODE					MENT NYM				CLA CO		N	IUMBI	ER	TYPE	
	0	3	R	ı	Р	S					Α	Α	0	0	1	М
Equipment Nomenclature Remote Image Processing System	<del>                                      </del>					Ві	ılletin m		name 0089		Occur	/				

Part or Component	Item	Task Statement and Instruction	Est.	Min.	Т	hreshold	ds
	No	(Comply with all current safety precautions)	Time		Run	Pieces	Freq.
			Req (min)	Lev	Hours	Fed (000)	
SAFETY		COMPLY WITH ALL SAFETY PRECAUTIONS.	1	All		(000)	-
STATEMENT	1.	Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Check for suspicious dust or unusual debris. If any unusual substance is found, notify supervisor prior to proceeding with any further action on the equipment.	•	7411			
		THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED. When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.					
		WARNING FOR EWP/PPE: Steps contained in this bulletin may require the use of Electrical Work Plan (EWP) Personal Protective Equipment (PPE). Refer to the current EWP MMO or appropriate EWP PPE and barricade requirements.					
		WARNING: Various products requiring Safety Data Sheets (SDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current SDS for each product used is on file and available to all employees. When reordering such a product, it is suggested that current SDS be requested. Refer to SDS for appropriate personal protective equipment.					

Part or Component	Item	Task Statement and Instruction	Est.	Min.	Т	hreshold	ds
	No	(Comply with all current safety precautions)	Time			Pieces	Freq.
			Req	Lev	Hours	Fed	
			(min)			(000)	
RIPS SYSTEM:	2.	Cleaning Front of RIPS	10	09			М
RIPS CABINET	۷.	CAUTION					
		To avoid damaging internal cabling, this task excludes opening the back of the RIPS cabinet and vacuuming interior.					
		Vacuum front of RIPS cabinet and fan port openings.					
		Clean keyboard and monitor using soft cloth.					
		3. Return cleaning tools to designated area.					
		4. Dispose of cleaning cloth appropriately.					

# **ATTACHMENT 3**

### **RIPS MASTER CHECKLIST**

### 09-RIPS-AA-001-M

# **OPERATIONAL MAINTENANCE (OM)**

Time Total: (16) minutes

U.S. Postal Service	IDENTIFICATION															
Maintenance Checklist	WORK EQUIPMENT CODE ACRONYM							•			CLA CO	ASS DE	N	UMBE	TYPE	
	0	9	R	ı	Р	S					Α	Α	0	0	1	М
Equipment Nomenclature Remote Image Processing System	Equipment Model						В		n Filer nm2	name 0089						

Part or Component	Item	Task Statement and Instruction	Est.	Min.		hreshold	ds
	No	(Comply with all current safety precautions)	Time		Run	Pieces	Freq.
			Req (min)	Lev	Hours	Fed	
SAFETY		COMPLY WITH ALL CAFETY PRECAUTIONS	1	All		(000)	
STATEMENT	1.	COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Check for suspicious dust or unusual debris. If any unusual substance is found, notify supervisor prior to proceeding with any further action on the equipment.	I	All			
		THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED. When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.					
		WARNING FOR EWP/PPE: Steps contained in this bulletin may require the use of Electrical Work Plan (EWP) Personal Protective Equipment (PPE). Refer to the current EWP MMO or appropriate EWP PPE and barricade requirements.					
		WARNING: Various products requiring Safety Data Sheets (SDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current SDS for each product used is on file and available to all employees. When reordering such a product, it is suggested that current SDS be requested. Refer to SDS for appropriate personal protective equipment.					

Part or Component	Item	Task Statement and Instruction	Est.	Min.		hreshold					
	No	(Comply with all current safety precautions)	Time Req (min)	Skill Lev	Run Hours	Pieces Fed (000)	Freq.				
RIPS SYSTEM: RIPS CABINET	2.	Front/Back Indicator Functionality Inspection	10			D					
T 6 6/12/11/21		If deficiencies are identified in any step below, contact the MTSC HelpDesk and open a ticket including all details.									
		Visual inspection of front indicator lights									
		<ol> <li>Ensure the server hard drive activity lights green or is flashing green. Reference MS-296 Figure 2-32 and table 2-14.</li> </ol>									
		Ensure NIC status LED is flashing     Reference MS-296 Figure 2-42 and table 2-17.									
		<ol> <li>Ensure 3PAR hard drive LEDs are green (16 on each 3PAR). Reference MS-296 Figure 2- 136 and table 2-23.</li> </ol>									
		<ol> <li>Ensure Uninterruptible Power Supply (UPS) is powered on. Reference MS-296 Figure 2-147 and table 2-26.</li> </ol>									
		Visual inspection of back indicator lights									
		<ol> <li>Verify all NIC ports with cables show flashing green on switches and servers Reference MS-296 Figures 2-13 and 2-73 and tables 2-8 and 2-19.</li> </ol>									
						<ol> <li>Verify all fiber ports with cables show flashing green on switches and servers. Reference MS- 296 Figures 2-13 and 2-73 and tables 2-8 and 2-19.</li> </ol>					
		<ol> <li>Verify both fiber ports on each 3PAR are flashing green for the link connection and flashing amber for the speed. Reference MS- 296 Figure 2-145 and table 2-25.</li> </ol>									