MAINTENANCE TECHNICAL SUPPORT CENTER / MAINTENANCE POLICIES & PROGRAMS **ENGINEERING / UNITED STATES POSTAL SERVICE**

Maintenance Management Order UNITED STATES POSTAL SERVICETM

SUBJECT: Preventive Maintenance Guidelines for DATE: May 17, 2006

Signode Bander

NO: MMO-055-06

TO: Maintenance Capable Offices FILE CODE: F8

same: mm06076aa

MAINTENANCE MANAGEMENT ORDER

This Maintenance Management Order (MMO) supersedes MMO-033-03. This MMO provides Preventive Maintenance (PM) guidelines for the Signode Bander with the corrected minimum skill levels.

The minimum maintenance skill level to perform each task on the various checklists is included in the Minimum Skill Level column. This does not preclude higher level employees from performing any of this work.

The work hours represented in this MMO reflect the maximum work hours required to maintain the equipment. Given local conditions, management may modify task frequencies.

WARNING

Various products which require Material Safety Data Sheets (MSDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current MSDS for each product used is on file and available by all employees. When reordering such a product, it is suggested that a current MSDS be requested. Refer to MSDS for appropriate personal protective equipment.

WARNING

The use of compressed or blown air is prohibited. When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used only on optical equipment when other cleaning methods can not be used.

Maintenance Managers are to use these Preventive Maintenance guidelines when preparing the route sheets for local maintenance personnel.

Web Access: https://www1.mtsc.usps.gov

For questions or comments concerning this bulletin contact the MTSC HelpDesk, either online at MTSC>HELPDESK>Create/Update Tickets or call (800) 366-4123.

Earl J. Jones Manager Maintenance Technical Support Center Maintenance Policies and Programs

Attachments: 1. Summary Workload Estimate

Signode Bander Master Checklist: 03-ASD-DA-001-M: Daily
 Signode Bander Master Checklist: 03-ASD-DA-002-M: Weekly
 Signode Bander Master Checklist: 03-ASD-DA-003-M: Monthly
 Signode Bander Master Checklist: 03-ASD-DA-004-M: Annual

MAINTENANCE MANAGEMENT ORDER

ATTACHMENT 1

SUMMARY

WORKLOAD ESTIMATE

FOR

SIGNODE BANDER

SUMMARY

WORKLOAD ESTIMATE FOR SIGNODE BANDER

	Routine		Total Servicing &	Nonproductive	Total Servicing Per
Days	Servicing	Repair*	Repair Time	Time **	Machine
per	(hrs/yr)	(hrs/yr)	(hrs/yr)	(hrs/yr)	(hrs/yr)
Week					
7 Day	214	21	235	23.5	258.5
6 Day	193	19	212	21.2	233.2
5 Day	172	17	189	18.9	207.9

- *Repair estimates based on 10% of servicing.
- **Based on 10% of servicing and repair.

PM CHECKLIST TIME SUMMARY

MAINTENANCE MANAGEMENT ORDER

Checklist	Checklist Times (per year)
03-ASD-DA-001-M (Daily)	8760 for 7 day/week
	7512 for 6 day/week
	6264 for 5 day/week
03-ASD-DA-002-M (Weekly)	3328 minutes
03-ASD-DA-003-M (Monthly)	648 minutes
03-ASD-DA-004-M (Annual)	74 minutes

ATTACHMENT 2

SIGNODE BANDER

03-ASD-DA-001-M

DAILY

Time Total: 24 Minutes

MIN

ΑII

U.S. Postal Service						IDENTIF	ICAT	ION				
Maintenance Checklist		ork de	Equipme Acrony						Number			Туре
		3	Α	S	D		D	Α	0	0	1	M
Equipment Nomenclature	Equi	ipme	nt Mc	del		Bulletin I	Filena	ame	Fred	quen	СУ	
Signode Bander		B 2	330	-LM	-	MM06	Daily			y		
		L	ISP:	S								

Part or	Item	Task Statement and Instruction	Est.	Min.
Component	No.	(Comply with all current safety precautions)	Time	Skill
·		, , , , , , , , , , , , , , , , , , ,	Req'd	Level

SAFETY STATEMENT

1.

COMPLY WITH ALL **SAFETY** PRECAUTIONS. Disconnect and power activate lockouts appropriate while working on this equipment. Open equipment and inspect dust conditions. Check to ensure all employees are clear of the machine by physically walking around the entire machine. Report safety deficiencies to your supervisor immediately upon detection. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp cloth, lint-free cloth or brush must be used in place of compressed or blown air. Report safety deficiencies to your supervisor immediately upon detection.

MACHINE

MAINTENANCE MANAGEMENT ORDER

2. **Power down and lockout power.** Power down the 2 All machine and lockout its electrical power as prescribed by MIN the current local lockout instructions providing lockout/restore procedures.

WARNING

Before working with or around hot knife allow knife to cool for 20 minutes.

3. Clean strapper.

10 6 MIN

- 1. Open both top covers.
- 2. Remove all debris especially around the sealing head, hot knife area, feed/tension wheels, infeed wheels, and accumulator box.
- 3. Use a stiff brush and HEPA filtered vacuum for cleaning.
- 4. Close top covers.

U.S. Postal Service						IDEN [*]	TIFIC	CATI	ON				
Maintenance Checklist		rk de	Equipm Acrony					Class Code		Number		er	Туре
	0	3	Α	S	D			D	Α	0	0	1	M
Equipment Nomenclature	Equip	ment	Mod	el		Bulletir	n File	enam	ne	Fred	uenc	у	
Signode Bander		3 23	30-l	_M-		MM(٩А	Daily			/		
ŭ		US	SPS									-	

Component	No.	(Comply with all current safety precautions)	Time Req'd	Skill Level
MACHINE	4.	Restore equipment to service. Restore equipment to service as prescribed by the current local procedure providing lockout/restore procedures.	2 MIN	6
	5.	Check strapping action of Signode Bander. Strap a tub and check for proper strap weld, tension, and cutoff.	2 MIN	8
CLEAN UP	6.	Clean up. Ensure all tools, lubricants, rags, etc., are removed from the work area. Report all deficiencies to your supervisor.	3 MIN	All

U.S. Postal Service						IDENTIF	TCA1	ION				
Maintanana Oksaldist	Wo	ork de		Eq	uipm							
Maintenance Checklist			Acronyr			m	C	ode	N	lumb	er	Type
		3	Α	S	D		D	Α	0	0	1	M
Equipment Nomenclature	Equ	ipme	nt Mo	del		Bulletin F	ilena	ame	Free	quen	су	
Signode Bander		B 2	330	-LIV	M- MM06		106076AA		Dail			/
_		L	SP	S								

Part or	Item	Task Statement and Instruction	Est.	Min.
Component	No.	(Comply with all current safety precautions)	Time	Skill
·			Req'd	Level

THIS PAGE BLANK

ATTACHMENT 3

SIGNODE BANDER

03-ASD-DA-002-M

WEEKLY

Time Total: 64 Minutes

MIN

ΑII

ΑII

6

20

MIN

U.S. Postal Service						IDEN	ITIFI	CAT	ION				
Maintenance Checklist		ork de	Equipme Acronyi					Class Code		Number			Туре
		3	Α	S	D			D	Α	0	0	2	M
Equipment Nomenclature	Equi	ipme	nt Mo	del		Bullet	tin F	ilena	me	Fred	quenc	у	
Signode Bander		LB 2330-LM-				MM06076AA					W	dy	
		l	SP	S									•

Part or	Item	Task Statement and Instruction	Est.	Min.
Component	No.	(Comply with all current safety precautions)	Time	Skill
·		, , , , , , , , , , , , , , , , , , ,	Req'd	Level

SAFETY STATEMENT

1.

COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and activate lockouts appropriate while working on this equipment. Open equipment and inspect dust conditions. Check to ensure all employees are clear of the machine by physically walking around the entire machine. Report safety deficiencies to your supervisor immediately upon detection. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp cloth, lint-free cloth or brush must be used in place of compressed or blown air. Report safety deficiencies to your supervisor immediately upon detection.

MACHINE

MAINTENANCE MANAGEMENT ORDER

2. **Power down and lockout power.** Power down the 2 machine and lockout its electrical power as prescribed by MIN the current local lockout instructions providing lockout/restore procedures.

WARNING

Before working with or around hot knife allow knife to cool for 20 minutes.

STRAP GUIDE AND PATH

3. Clean material path.

 Clean the feed/tension wheels and guides, and check for wear and/or damage. Report any deficiencies to the supervisor.

- 2. Clean the strap dust from strap path and accumulator box with soft brush.
- 3. Remove anvil head and clean strap dust from 1PRS lever assembly.

U.S. Postal Service						IDENTIFI	CATI	ON				
Maintenance Checklist		rk de	Equipr Acron				Class Code		Number			Туре
	0	3	Α	S	D		D	Α	0	0	2	M
Equipment Nomenclature Signode Bander		3 23	nt Model 330-LM- ISPS			Bulletin Fil MM060			Frequency Week			dy

Part or	Item	Task Statement and Instruction	Est.	Min.
Component	No.	(Comply with all current safety precautions)	Time	Skill
•			Rea'd	Level

WARNING

The use of compressed or blown air is prohibited. When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used only on optical equipment when other cleaning methods can not be used.

WARNING

Before working with or around hot knife allow knife to cool for 20 minutes.

STRAP	4.	Strap welding.	30 MIN	6
		 Clean hot knife's top and bottom surfaces using fine grit emery paper. 	IVIIIN	
		2. Clean surrounding area with soft brush and HEPA vacuum.		
MACHINE	5.	Restore equipment to service. Restore equipment to service as prescribed by the current local procedure providing lockout/restore procedures.	2 MIN	6
	6.	Check the strapping action of the Signode Bander. Strap a tub and check for proper strap weld, tension, and cutoff.	2 MIN	8
CLEAN UP	7.	Clean up. Ensure all tools, lubricants, rags, etc., are removed from the work area. Report all deficiencies to	3 MIN	All

your supervisor.

U.S. Postal Service	IDENTIFICATION												
Maintenance Checklist		Work Code		Equipm Acrony				Class Code		Number			Туре
	0	3	Α	S	D			D	Α	0	0	2	M
Equipment Nomenclature	Equipment Model					Bullet	tin F	ilena	me	Frequency			
Signode Bander		LB 2330-LM-				MM	1060	076	AA	Weekly			dy
<u> </u>		L	SP	S									J

Part or	Item	Task Statement and Instruction	Est.	Min.
Component	No.	(Comply with all current safety precautions)	Time	Skill
·			Req'd	Level

THIS PAGE BLANK

ATTACHMENT 4

SIGNODE BANDER

03-ASD-DA-003-M

MONTHLY

Time Total: 54 Minutes

MIN

ΑII

U.S. Postal Service	IDENTIFICATION												
Maintenance Checklist		Work Code		Equipm Acrony				Class Code		Number			Туре
	0	3	Α	S	D			D	Α	0	0	3	M
Equipment Nomenclature	Equipment Model					Bullet	tin F	ilena	me	Frequency			
Signode Bander		LB 2330-LM-					1060	076	AA	Monthly			nly
<u> </u>		L	SP	S									•

Part or	Item	Task Statement and Instruction	Est.	Min.
Component	No.	(Comply with all current safety precautions)	Time	Skill
·			Req'd	Level

SAFETY STATEMENT

1.

COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and activate lockouts as appropriate while working on this equipment. Open equipment and inspect dust conditions. Check to ensure all employees are clear of the machine by physically walking around the entire machine. Report safety deficiencies to your supervisor immediately upon detection. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp cloth, lint-free cloth or brush must be used in place of compressed or blown air. Report safety deficiencies to your supervisor immediately upon detection.

MACHINE

MAINTENANCE MANAGEMENT ORDER

2. **Power down and lockout power.** Power down the 2 machine and lockout its electrical power as prescribed by MIN the current local lockout instructions providing lockout/restore procedures.

WARNING

Before working with or around hot knife allow knife to cool for 20 minutes.

3. Check machine.

40 8 MIN

ΑII

- 1. Check bearings for freedom of movement.
- 2. Check cams for wear.
- 3. Check clutch sheave and outer clutch plate for free movement. Check slip washers for proper function (replace if they don't return to original color after cleaning). Adjust clutch if necessary.

6

U.S. Postal Service	IDENTIFICATION												
Maintenance Checklist		Work Code				nent iym	Class Code		Number			Туре	
	0	3	Α	S	D		D	Α	0	0	3	M	
Equipment Nomenclature Signode Bander	Equip LE	3 23	Mod 30- SPS	LM-		Bulletin Fil MM060			Fred	queno M	y onth	nly	

Part or	Item	Task Statement and Instruction	Est.	Min.
Component	No.	(Comply with all current safety precautions)	Time	Skill
·			Req'd	Level

- 4. Check the urethane tension wheel for any possible damage. If excessive grooving takes place or gouges are happening, replace.
- 5. Check entire chute assembly for proper operation and alignment with head.
- 6. Check for loose electrical connections.
- 7. Check the accumulator box limit switch for proper operation.
- 8. Tighten all screws.
- MACHINE 4. Restore equipment to service. Restore equipment to 2 service as prescribed by current local procedure MIN
 - providing lockout/restore procedures.
 - 5. Check strapping action of Signode Bander. Strap a 2 8 tub and check for proper strap weld, tension, and cutoff. MIN
- CLEAN UP 6. **Clean up.** Ensure all tools, lubricants, rags, etc., are 3 All removed from the work area. Report all deficiencies to MIN your supervisor.

U.S. Postal Service						IDENTIF	ICAT	ION				
Maintenance Checklist		ork Equipme ode Acronyr						Number			Туре	
	0	3	Α	S	D		D	Α	0	0	3	M
Equipment Nomenclature	Equi	ipmeı	nt Mo	del		Bulletin F	ilena	me	Frequency			
Signode Bander		LB 2330-LM-				MM06	076	AA	Monthly			nly
		U	SP	S								-

Part or	Item	Task Statement and Instruction	Est.	Min.
Component	No.	(Comply with all current safety precautions)	Time	Skill
·			Req'd	Level

THIS PAGE BLANK

ATTACHMENT 5

SIGNODE BANDER

03-ASD-DA-004-M

ANNUAL

Time Total: 74 Minutes

MIN

ΑII

6

U.S. Postal Service	IDENTIFICATION												
Maintenance Checklist		ork de	1. 1					Class Code		Number		er	Туре
	0	3	Α	S	D			D	Α	0	0	4	M
Equipment Nomenclature	Equipment Model					Bulle	etin F	ilena	me	Frequency			
Signode Bander		LB 2330-LM-					106	076	AA	Annual			al
_	USPS												

Part or	Item	Task Statement and Instruction	Est.	Min.
Component	No.	(Comply with all current safety precautions)	Time	Skill
·			Req'd	Level

SAFETY STATEMENT

1.

COMPLY WITH ALL **SAFETY** PRECAUTIONS. Disconnect power activate and lockouts appropriate while working on this equipment. Open equipment and inspect dust conditions. Check to ensure all employees are clear of the machine by physically walking around the entire machine. Report safety deficiencies to your supervisor immediately upon detection. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp cloth, lint-free cloth or brush must be used in place of compressed or blown air. Report safety deficiencies to your supervisor immediately upon detection.

MACHINE

MAINTENANCE MANAGEMENT ORDER

 Power down and lockout power. Power down the machine and lockout its electrical power as prescribed by current local lockout instructions providing lockout/restore procedures.

WARNING

Before working with or around hot knife allow knife to cool for 20 minutes.

3. Check machine.

60 MIN

8

MIN

- 1. Check the electrical enclosure gasket for wear or damage. Replace if necessary.
- 2. Check head assembly. Replace loop grip pivot arm assembly.
- 3. Check head pivot shaft and bearings (replace if necessary).

MACHINE

4. **Restore equipment to service.** Restore equipment to 2 4 service as prescribed by the current local procedure MIN providing lockout/restore procedures.

U.S. Postal Service		IDENTIFICATION													
Maintenance Checklist		ork		Eq	uipm	nent		Cla	ass						
		de	Acronym			Co	Code		Number		Type				
	0	3	Α	S	D			D	Α	0	0	4	M		
Equipment Nomenclature	Equi	Equipment Model					Bulletin Filename					Frequency			
Signode Bander		LB 2330-LM-			-	MM	4Α		Α	al					
-		USPS													

Part or	Item	Task Statement and Instruction	Est.	Min.
Component	No.	(Comply with all current safety precautions)	Time	Skill
•			Req'd	Level

5. **Check strapping action of Signode Bander.** Strap a 2 8 tub and check for proper strap weld, tension, and cutoff. MIN

CLEAN UP

MAINTENANCE MANAGEMENT ORDER

 Clean up. Ensure all tools, lubricants, rags, etc., are 3 All removed from the work area. Report all deficiencies to MIN your supervisor.