# MAINTENANCE TECHNICAL SUPPORT CENTER **HEADQUARTERS MAINTENANCE OPERATIONS**





# Maintenance Management Order

**SUBJECT:** Tray Sorting Machine Novasort Preventive **DATE:** December 18, 2013

Maintenance

**NO:** MMO-112-13

**TO:** Tray Sorting Machine Novasort Sites FILE CODE: TM

pmur:mm13052ab

This Maintenance Management Order (MMO) provides Preventive Maintenance Guidelines for the Tray Sorting Machine Novasort System (TSM). This bulletin applies to Acronym TSM, Class Code CA.

The workhours indicated in the workload estimate (Attachment 1) reflect the *maximum* annual workhours required to maintain each system. Management may modify task frequencies to address local conditions.

The minimum maintenance skill level required to perform each task is included in the Minimum Skill Level column of each checklist. This does not preclude higher level employees from performing any of this work.

# WARNING

Various products requiring Material Safety Data Sheets (MSDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current MSDS for each product used is on file and available to all employees. When reordering such a product, it is suggested that current MSDS be requested. Refer to MSDS for appropriate personal protective equipment.

# WARNING

The use of compressed or blown air is prohibited. An alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp rag, lint-free cloth, or brush must be used in place of compressed or blown air.

Web Access: http://mtsc.usps.gov

# WARNING

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

For questions or comments concerning this bulletin contact the MTSC HelpDesk, either online at MTSC>HELPDESK>Create/Update Tickets or call (800) 366-4123.

Robert E. Albert

Manager

Maintenance Technical Support Center

**HQ** Maintenance Operations

- Attachments 1. Summary of Workload Estimate
  - 2. Master Checklist: 03-TSM-CA-001-M: Quarterly PM

# **ATTACHMENT 1**

**SUMMARY** 

**WORKLOAD ESTIMATE** 

FOR

**TSM SYSTEM** 

# SUMMARY WORKLOAD ESTIMATE FOR TSM

	Routine Servicing (Hrs/Yr)	Repair* (Hrs/yr.)	Total Servicing & Repair Time (Hrs/Yr)	Nonproductive Time** (Hrs/Yr)	Total Servicing Per Unit (Hrs/Yr)
Quarterly	1.93	0.77	2.70	0.27	2.97

#### **NOTES**

- \*Repair estimates based on 40% of servicing.
- \*\*Based on 10% of total servicing and repair.

### **NOTE**

The time shown does not allow for multiple assemblies on any equipment. Should multiple assemblies exist, the time must be modified at the local level to account for those occurrences. Other unique site conditions that require additional time are also to be addressed at the local level.

# **ATTACHMENT 2**

# **TSM MASTER CHECKLIST**

03-TSM-CA-001-M

Quarterly Time Total: 29 minutes

Maintenance Technical Support Center

U.S. Postal Service		IC						IDE	IDENTIFICATION								
Maintenance Checklist	_	DRK DDE					MEN NYM				CLASS CODE		NUMBER			TYPE	
	0	3	Т	S	М						С	Α	0	0	1	М	
Equipment Nomenclature Tray Sorting Machine Novasort	Equ	ipmeı	nt Mo	del				В		n Filer m13	name 052ab		Occurr		arter	ly	

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	S
Component	No	(Comply with all current safety precautions)	Time Req (min)	Skill Lev	Run Hours	Pieces Fed (000)	Freq.
SAFETY STATEMENT		COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.	3	All			
		THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED. When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.					
		WARNING FOR EWP/PPE: Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.					
		Lock Out Power.  Place appropriate PLC control panel "AUTO/MANUAL" switch in the "MANUAL" position. Lock out electrical power by placing the PLC disconnect lever in the "OFF" position and installing a LOCKOUT/TAGOUT device.	2	All			
DISCHARGE CHUTE		<ol> <li>Check Discharge Chute.</li> <li>Visually check for any damage (large gouges or cracking) to the fiberglass chute.</li> <li>Remove foreign objects (i.e., tape, labels, string, rubber bands, etc.) from the interior.</li> <li>Report discrepancies to supervisor.</li> </ol>	3	7			

U.S. Postal Service			IDENTIFICATION													
Maintenance Checklist		RK DE					MEN <sup>-</sup>				_	ASS DE	N	UMBI	ĒR	TYPE
	0	3	Т	S	М						С	Α	0	0	1	М
Equipment Nomenclature Tray Sorting Machine Novasort	Equ	ipmer	nt Mo	del				E	Bulletin m		name 052ab		Occuri		arter	ly

Part or	Item	Task Statement and Instruction	Est.	Min.		Thresholds	
Component	No	(Comply with all current safety precautions)	Time	Skill			
			Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.
PHOTO SENSORS AND REFLECTORS		<ol> <li>Check Photo Sensors, Reflectors, and Infrared Emitters.</li> <li>Check the photo sensor, reflector, and/or infrared emitter for physical damage.</li> <li>Check the mounting connections for tightness. If loose, tighten the connections.</li> <li>Check the electrical connections for tightness.</li> <li>Report discrepancies to supervisor.</li> </ol>	4	7			
		Clean Photo Sensors, Reflectors, and Infrared Emitters.  1. Wipe the photo sensor/emitter window with a damp rag to remove dust and dirt.  2. Wipe the reflector with a damp rag to remove dust and dirt.  3. Wipe the emitter window with a damp rag to remove dust and dirt.	4	7			
DISCHARGE CHUTE	6.	Ensure the current MSDS for Odorless Mineral Spirits (or equivalent) is on file and available to all employees. When reordering such a product, it is suggested that current MSDS be requested. Refer to MSDS for appropriate personal protective equipment.  WARNING  Ensure the current MSDS for Pledge Furniture Polish (or equivalent) is on file and available to all employees. When reordering such a product, it is suggested that current MSDS be requested. Refer to MSDS for appropriate personal protective equipment.	5	7			

Maintenance Technical Support Center

U.S. Postal Service								IDENTIFICATION									
Maintenance Checklist		ORK ODE					MEN.					ASS DE	N	UMBI	ΞR	TYPE	
	0	3	Т	S	М						С	Α	0	0	1	М	
Equipment Nomenclature Tray Sorting Machine Novasort	Equ	ipmeı	nt Mo	del				В			name 052ab		Occuri		arter	ly	

ray coraing ma	ichine ivo	783011	mm1305	Zab	,		Quarteriy	/
Part or	Item	Task Statement and Instruction		st.	Min.		Thresholds	6
Component	No	(Comply with all current safety precaution	R	me eq nin)	Skill Lev	Run Hours	Pieces Fed (000)	Fr
		Discard or dispose of chemical s materials according to MSDS a accordance with local procedures.	ind in					
		WARNING						
		Do not ride in the chute. Pe injury could result from riding in c	rsonal hute.					
		1. Remove loose material from the chu	ıte.					
		2. Remove surface contamination Odorless Mineral Spirits (or equivathe inside surface of the chute. liquid using clean dry cloth, ensuinside surface is wiped. Contaminate removed during this process may be on the cloth. Continue to wipe inside of the chute until dirty residue is present on the cloth being used to the Mineral Spirits. The inside surthen be wiped again with a dry clear remove all excess Mineral Spirits accumulated on the surface.	valent) on Distribute ure entire ants being be present de surface no longer distribute face shall an cloth to					
		3. Perform a complete check of the surface of the chute. Materials grease or oil may be difficult to se surface. This problem can be comby lighting arrangements, so it is computed the surface be looked at from sever of any material is found at this check previous step until material is compressed from the chute surface.	such as ee on the inpounded ritical that ral angles. ck, repeat					
		4. Treat surface using Pledge Furnitu (or equivalent) on the inside surfachute. Distribute polish using a cloth. Do not spray the polish direction the inside surface of the chute. So the cloth and wipe the chute with Ensure the entire inside surface Wipe the inside surface again wo clean cloth to remove all access pray have accumulated on the surface.	cce of the clean dry ectly onto pray onto the cloth. is wiped. with a dry polish that					

U.S. Postal Service							ID	ENTIF	ICAT	ION					
Maintenance Checklist		RK DE				 MEN <sup>*</sup>				_	ASS DE	N	UMBI	ΞR	TYPE
	0	3	Т	S	М					С	Α	0	0	1	M
Equipment Nomenclature Tray Sorting Machine Novasort	Equ	ipmer	nt Mo	del			E	Bulletir m		name 052ab		Occuri		arter	ly

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	s
·			Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.
		5. Report discrepancies to supervisor.					
DISCHARGE	7.	Test Discharge Chute.	3	7			
CHUTE		Test the chute with 5 trays of mail. Ensure trays slide smoothly and do not hang up. Report discrepancies to supervisor.					
		WARNING  Be cautious when working around or on equipment when power has been applied.					
	8.	Restore Equipment To Service.  Restore electrical power by removing your LOCKOUT/TAGOUT device and placing the PLC disconnect lever in the "ON" position. Place the PLC control panel "AUTO/MANUAL" switch in the "AUTO" position.	2	All			
CLEAN UP	9.	Clean Up. Ensure all tools, lubricants, rags, etc., are removed from the work area. Report all deficiencies to your supervisor.	3	All			