MAINTENANCE TECHNICAL SUPPORT CENTER HEADQUARTERS MAINTENANCE OPERATIONS UNITED STATES POSTAL SERVICE

Maintenance Management Order POSTAL SERVICETM

SUBJECT: Preventive Maintenance Guidelines for

Overhead Scanning Solution Tracking

System (OSSTS) Workstation

DATE: June 8, 2012 **NO:** MMO-067-12

FILE CODE: R6

dtod:mm10038ac

TO: All Overhead Scanning Solution Tracking

System Workstation Sites

This MMO provides Preventive Maintenance (PM) guidelines for the Overhead Scanning Solution Tracking System Workstation (OSSTS). The eMARS acronym is OSSTS. Class Code is AA.

The minimum maintenance skill level to perform each task on the various checklists is included in the Minimum Skill Level column. This does not preclude higher level employees from performing any of this work.

The work hours represented in this MMO reflect the maximum work hours required to maintain the equipment. Given local conditions, management may modify task frequencies.

WARNING

Various products requiring Material Safety Data Sheets (MSDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current MSDS for each product used is on file and available to all employees. When reordering such a product, it is suggested that current MSDS be requested. Refer to MSDS for appropriate personal protective equipment.

Web Access: https://www1.mtsc.usps.gov

WARNING

The use of compressed or blown air is prohibited. An alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp rag, lint-free cloth, or brush must be used in place of compressed or blown air.

For questions or comments concerning this bulletin contact the MTSC HelpDesk, either online at MTSC>HELPDESK>Create/Update Tickets or call (800) 366-4123.

Robert E. Albert

Manager

Maintenance Technical Support Center

HQ Maintenance Operations

Attachments: 1. Summary Workload Estimate for OSSTS

2 OSSTS Master Checklist: 03-OSSTS-AA-001-M: Weekly

3 OSSTS Master Checklist: 03-OSSTS-AA-002-M: Monthly

ATTACHMENT 1

SUMMARY

WORKLOAD ESTIMATE

FOR

OSSTS

SUMMARY WORKLOAD ESTIMATE FOR OSSTS

| Days | Routine Servicing (hrs/yr) | Repair* (hrs/yr) | Total Servicing & Repair Time (hrs/yr) | Nonproductive Time** (hrs/yr) | Total Servicing Per Machine (hrs/yr) |
|-------|----------------------------------|---------------------|---|----------------------------------|---|
| 5 Day | 19.07 | 5.72 | 24.79 | 2.48 | 27.27 |
| 6 Day | 19.07 | 5.72 | 24.79 | 2.48 | 27.27 |
| 7 Day | 19.07 | 5.72 | 24.79 | 2.48 | 27.27 |

^{*} Repair estimates based on 30%.
** Based on 10% of total servicing and repair.

ATTACHMENT 2

OSSTS MASTER CHECKLIST

03-OSSTS-AA-001-M

WEEKLY

Time Total: 19 Minutes

Maintenance Technical Support Center

| U.S. Postal | Service | | | | | | IDENTIFICAT | ΓΙΟΝ | | | | | | |
|---|---------|--|--|---|--|--|---|----------------------|--------------|----------------------|---------------|-------|--|--|
| Maintenance | | klist | WORK CODE | | | JIPMENT RONYM | CL | ASS DDE | NU | MBER | TYPE | | | |
| | | | 0 3 | O S | S | ГВ | | Α | Α | 0 | 0 1 | М | | |
| Equipment Nomenclature Overhead Scanr Tracking System | ning So | | Equipme | ent Model | | | Bulletin File | ename 0038A0 | | Occurrence Weekly | | | | |
| Part or | Item | | | Statement | | | > | Est. | Min. | | ls | | | |
| Component | No | | Comply w | ith all curre | nt sarety | precautio | ns) | Time Req (min) | Skill Lev | Run Hours | Pieces Fed | Freq. | | |
| | | | | | | | | (*****) | | 110010 | (000) | | | |
| | | | | | | | | | | | | | | |
| SAFETY STATEMENT | 1. | Discontrequired local lo | nect por d by this ockout and loce ent and or susp unusual sor pri action of E OF Con HIBITED cleaning g meth ocleane | wer and s instruction to proceduct to inspect to perform the equipment of | apply ction. Ires to this meet did ust or ance in proceed quipme SSED Country as a amp rad or bl | lockou Refer to prope achine. ust col unusua is foun ding w nt. DR BLO an ali HEPA g must own air | nditions. Il debris. d notify vith any | 5 | All | | | | | |
| | | equipm method | ent o s can icies to | nly wh not be your si | en d used. | ther Repo | cleaning rt safety nediately | | | | | | | |
| | | | | WARI | NING | | | | | | | | | |
| | | | quipme | when the | | | | | | | | | | |
| POWER ON | 2. | Power of | on. | | | | | 1 | All | | | | | |
| | | lock clock lf power plug 2. Power plug bee | out box kwise to wer locker, ensuged into ver on Eleft side of indicated box does | the ON kout box ire power | ng the coposition does not cable ity suppose Lister has been detailed. | disconners. ot supply connect plied power switch for aud been apply check p | y system or is wer drop. I located lible olied. | | | | | | | |

| U.S. Postal S | Service | | | | | | | DENTIFICA | | | C NUMBER T | | | |
|---------------------------------------|---------|--------------------|---------------------|---|--------|--------|--------------|---------------------|----------------|--------------|------------|---------------|------|--|
| Maintenance | Chec | klist | WORK CODE | | | | MENT DNYM | | | LASS ODE | NU | MBER | TYPE | |
| | | | 0 3 | 0 S | S | Т | S | | Α | Α | 0 | 0 1 | М | |
| Equipment Nomenclature Overhead Scann | | lution | Equipme | nt Model | | | | Bulletin Fil MM1 | ename 0038A | c | Occurre | nce Weekly | y | |
| Tracking System | | | | | | | | | | | | | | |
| Part or | Item | | | Statement | | | | | Est. | Min. | | ds | | |
| Component | No | ((| Comply wit | th all currer | nt saf | ety pr | ecautio | ns) | Time Req | Skill Lev | | | | |
| | | | | | | | | | (min) | | | | | |
| | | | ſ | | | | | | | | | | | |
| | | | | CAUT | ION | | | | | | | | | |
| | | | | re into | | | | | | | | | | |
| | | | | empts to ight on | | | | axis, | | | | | | |
| | | over | riding t | he nati | ural | bli | nking | | | | | | | |
| | | | | oking a g a bri | | | | | | | | | | |
| | | Used | l proper | ly, Classidered | s II | lase | r pro | ducts | | | | | | |
| | | | | vould ca | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | scanner | | | | | | | | | | |
| | | | station s | oattern is surface. | illur | nına | tea on | | | | | | | |
| | | | | scan pa cable to | | | | ble, | | | | | | |
| | | 4. Veri | | nonitor is e Operat | | | | | | | | | | |
| | | | | not power and da | | | | • | | | | | | |
| | | upon bo | ot up. In he MPE | ode is the this mod ID, RUN | de, t | he s | creen | will | | | | | | |
| E-BOX | 3. | E-Box v | isual ch | eck. | | | | | 0.5 | 7 | | | | |
| | | Visually indicatio | | -Box disp | olay | for th | ne follo | owing | | | | | | |
| | | 1. EES | S-00x <i>(</i>) | c = chanr | nel ra | ange | : 001 | to 008 | | | | | | |
| | | sele swite | ct the co | channel i rrect cha t side of l l. | nne | l usir | ng the | rotary | | | | | | |
| | | 2. Curr | ent date | and time | Э | | | | | | | | | |
| | | pow the o | er to the | date or tir E-box, if me, cont | this | doe | s not o | | | | | | | |

OVERHEAD

SCANNERS

5

7

| MMO-067-12 | | | | | | | | | - 1 | Иa | inte | nar | ice T | echr | nical S | Suppo | rt C | <u>ente</u> |
|---|------------|--------------|-------------------|--|-------|-----|-------|-------|------------------|------|-----------------------|-----|--------------|---------------|--------------|------------------------|------|-------------|
| U.S. Posta | al Service | | | | | | | | | IDE | NTIF | CAT | | | | | | |
| Maintenanc | e Chec | klist | | ORK ODE | | | | | MENT DNYM | | | | _ | LASS ODE | NUMBER | | | YPE |
| | | | 0 | 3 | 0 | S | S | Т | S | | | | Α | Α | 0 | 0 1 | | M |
| Equipment Nomenclate Overhead Scal Tracking Syste | nning So | | Equ | ipmeı | nt Mo | del | | | 1 | В | ulletin M l | | name 038A | С | Occurre | week | ly | |
| Part or Component | Item No | (| | | State | | | | ction ecautio | ns) | | | Est. Time | Min. Skill | | Thresho | lds | |
| · | | , | | · | | | | | | ŕ | | | Req (min) | Lev | Run Hours | Pieces Fed (000) | F | req. |
| | | 3. DCS | S: CC | NNC | ECT | ED. | | | | | | | | | | | | |
| | | coni netv | necti vork | S shows disconnected, inspect the ections for the network cable drop, the rk cabling between the power lockout and Ebox port J2 WAN. | | | | | | | | | | | | | | |
| E-SWITCH | 4. | Start ru | n. | | | | | | | | | | 0.5 | 7 | | | | |
| | | | ss S ⁻ | | T/ST | OP | butte | on oi | n E-S | wito | ch to | | | | | | | |

If START/STOP button on E-Switch does not begin and / or end a run, check the connections for the network cable between the E-switch and the network router and power cycle the E-switch by disconnecting

and reconnecting the power supply connector on top-side of E-switch.

2. Check overhead LCD monitor for current

Use the Barcode Test Mailpiece* to perform scan test on each overhead scanner while in

* Refer to MMO-070-12 for Barcode Test Sheet

1. Scan Barcode Test Sheet 1 for Scanner 1.

increment at P1.

increment at P1.

Ensure scanner responds with an audible tone and green LED flash.

Check the LCD monitor for COUNTS

Scan Barcode Test Sheet 2 for Scanner 2.

Ensure scanner responds with an audible tone and green LED flash.

Check the LCD monitor for COUNTS

date and time.

Operational Mode.

Preparation.

Overhead Scanner scan test.

5.

IDENTIFICATION

| Maintenance | Chec | klist | WORK CODE | | EQUIF ACRO | | | LASS ODE | NUI | TYPE | | |
|------------------------|--------|-----------|-------------------------|---------------|---------------|---------|------------------------|-------------|--------------|---------|-----------|----|
| airitoriarioe | J1100 | | 0 3 | o s | ST | S | | A | A | 0 | 0 1 | М |
| Equipment Nomenclature | ! | | Equipmer | | . | | Bulletin File | | | Occurre | | |
| Overhead Scann | ing So | | | | | | MM10 | | | | Weekly | / |
| Tracking System | vvorks | tation | | | - | - | | | | | | |
| Part or | Item | | | Statement a | | | | Est. | Min. | | Threshold | ds |
| Component | No | (| (Comply wit | h all current | t safety pr | ecautio | ns) | Time Req | Skill Lev | | | |
| | | | | | | | | (min) | LEV | | | |
| | | 3. Sca | ın Barcod | a Tast Sh | 100t 3 fo | or Scar | nner 3 | | | | | |
| | | J. 30a | iii Dalcou | 0 163131 | IGGL J IC | n Ocal | iiilei J. | | | | | |
| | | a. | | scanner | | | | | | | | |
| | | | audible | tone and | green | LED fla | ash. | | | | | |
| | | b. | Check | the LCD r | monitor | for CC | DUNTS | | | | | |
| | | | | ent at P1. | | | | | | | | |
| | | V 15.71- | 0 Overb - | ad Casar | \0r 000 | toot f | oile | | | | | |
| | | | e Overhe | | | | | | | | | |
| | | com | nponents | for power | r by che | | | | | | | |
| | | indi | cators for | illuminati | ion: | - | | | | | | |
| | | a. | 8-Port I | Multiplexo | or MI800 |)8 | | | | | | |
| | | b. | Etherne | et Router | | | | | | | | |
| | | C. | Multipo | int Acces | s Hub N | /ISP10 | 000 | | | | | |
| | | If one or | r more of | the comp | onents | are no | ot | | | | | |
| | | powered | d on, che | ck the po | wer cab | le con | nection | | | | | |
| | | | n power s witch whe | | | | | | | | | |
| | | | , contact | | | | 0111 | | | | | |
| LIANDUELD | | _ | | | | | m fa = 1 | | | | | |
| HANDHELD SCANNERS | 6. | | BT handh | • | | | | 5 | 7 | | | |
| 33/11112110 | | | this prod | | | | | | | | | |
| | | nandhe | ld scanne | er using B | arcode | rest S | oneet 6 [*] . | | | | | |
| | | | to MMO-0 |)70-12 fo | r Barcoo | de Tes | st Sheet | | | | | |
| | | Prepara | ıtion. | | | | | | | | | |
| | | | | | | | sary, into | | | | | |
| | | | | | | | ower on | | | | | |
| | | | nner usin andle. | g power | button I | ocated | d at base | | | | | |
| | | 0,11 | ariaio. | | | | | | | | | |
| | | | | | | rcode | #1 with | | | | | |
| | | han | dheld sca | anner #1. | | | | | | | | |
| | | a. | Verify s | scanner re | esponds | to sca | an with | | | | | |
| | | | | ible tone a | | | | | | | | |
| | | b. | Check | system Lo | CD mon | itor fo | r scan | | | | | |
| | | J. | | ncrement | | | . 55411 | | | | | |
| | | 0.0 | ъ Г ' | DT C | <u>-</u> - | المحاد | до: и | | | | | |
| | | | ın Focusi Idheld sca | | ner Ba | rcode | #2 with | | | | | |
| | | Han | G11010 300 | πΔ. | | | | | لــــــــا | | | 1 |

Maintenance Technical Support Center

| U.S. Postal S | Service | | | | | | IDENTIFICAT | | | 00 11111000 | | |
|---|---------|------------------------------------|--|---|--|---|---|----------------------|--------------|---------------|------------------------|-------|
| Maintenance | Chec | klist | WORK CODE | | | JIPMENT RONYM | | | ASS ODE | NL | IMBER | TYPE |
| | | | 0 3 | 0 S | S | ΤЅ | | Α | Α | 0 | 0 1 | М |
| Equipment Nomenclature Overhead Scann Tracking System | ing So | | Equipme | nt Model | I I | , 1 | Bulletin File MM10 | ename 0038A0 | С | Occurre | ence Weekly | / |
| Part or | Item | | | Statement | | | | Est. | Min. | | Threshold | ds |
| Component | No | ((| Comply wit | th all currer | nt safety | precautio | ns) | Time Req (min) | Skill Lev | Run Hours | Pieces Fed (000) | Freq. |
| | | b. 5. Scar hand a. b. 6. Pow at b. | an aud Check count in Focus dheld sca Verify s an aud Check count in Focus dheld sca Verify s an aud Check count in coun | scanner #3. scanner rible tone system L scanner #4. scanner rible tone system L ncremen | and w CD m t at J1. respon and w CD m t at J1. respon and w CD m t at J1. respon and w | white LEI onitor for Barcode ads to so white LEI onitor for coarcode dids to so white LEI onitor for coarcode and to so white LEI onitor for coarcode | #3 with an with or scan #4 with an with or scan #4 with an with of flash. | | | | | |
| CLEAN UP | 7. | from the | all tools work are use. Re | ea and s | tored | in a safe | removed e area for to your | 2 | All | | | |

ATTACHMENT 3

OSSTS MASTER CHECKLIST

03-OSSTS-AA-002-M

MONTHLY

Time Total: 13 Minutes

Maintenance Technical Support Center

ΑII

1

| U.S. Postal Service | | | IDENTIFICATION | | | | | | | | | | | | | |
|------------------------|--------------|-------------|----------------|----------------------|---|---|---|---|----------|-------|------|-----------|--------|------|---|------|
| Maintenance Checklist | WORK CODE | | | EQUIPMENT ACRONYM | | | | | | | | ASS DE | NUMBER | | | TYPE |
| | 0 | 3 | 0 | S | S | Τ | S | | | | Α | Α | 0 | 0 | 2 | М |
| Equipment Nomenclature | Equ | Equipment M | | nt Model | | | | Е | Bulletir | Filer | name | | Occuri | ence | | |
| | | | | | | | | | ΜN | 110 | 038A | С | | | | |

| | | 1111111 | | | | | |
|----------------------|------------|--|------------------------------|----------------------|--------------|----------------------|----------|
| Part or Component | Item No | Task Statement and Instruction (Comply with all current safety precautions) | Est. Time Req (min) | Min. Skill Lev | Run Hours | Threshold Pieces Fed | s Fre |
| | | | , , | | | (000) | |
| SAFETY STATEMENT | 1. | COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment. | 5 | All | | | |
| | | THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED. When cleaning is required, an alternative cleaning method such as a HEPA filtered | | | | | |

in place of compressed or blown air. A lintfree cloth or brush may be used on optical equipment only when other cleaning methods can not be used. Report safety deficiencies to your supervisor immediately upon detection. OSSTS 2. Power down and lock out power. 1 ΑII Power down and lock out the equipment as prescribed by local lockout/restore procedures. 3. Overhead Scanner lens cleaning. 5

vacuum cleaner or a damp rag must be used

Do not clean scanning lenses with solvents such as alcohol or acetone. These materials can damage the camera scanning lens.

CAUTION

Use a lint-free non-abrasive cleaning cloth to gently clean each Overhead Scanner lens and each Bluetooth Handheld Scanner lens.

removed from the machine and work area.

CLEAN UP

4. Clean up.
Ensure all tools and cleaning materials are

MMO-067-12

| U.S. Postal Service | IDENTIFICATION | | | | | | | | | | | | | | | |
|------------------------|----------------|----------|-------|-----|---|---------------|---|--|--------------------------------|--|---|-----------|--------|----|------|---|
| Maintenance Checklist | _ | RK DE | | | | EQUIF ACRO | | | | | _ | ASS DE | N | ĒR | TYPE | |
| | 0 | 3 | 0 | S | Т | S | S | | | | Α | Α | 0 | 0 | 2 | М |
| Equipment Nomenclature | Equ | ipmer | nt Mo | del | | | | | Bulletin Filename MM10038AC | | | С | Occuri | | | |

| Part or Component | Item No | Task Statement and Instruction (Comply with all current safety precautions) | Est. Time | Min. Skill | | Threshold | S |
|----------------------|------------|--|--------------|---------------|--------------|------------------------|-------|
| , | | | Req (min) | Lev | Run Hours | Pieces Fed (000) | Freq. |
| | | WARNING Be cautious when working around or on equipment when power has been applied. | | | | | |
| OSSTS | 5. | Restore equipment to service. Restore equipment to service as prescribed by local lockout/restore procedures. | 1 | All | | | |