

THE DEPARTMENT OF
MINES AND PETROLEUM RESOURCES



WHEN REPLYING PLEASE REFER TO

FILE NO.

2226 Brotharstone Rd.
Nanaimo, B. C. V9S 3M8

June 10, 1977

Mr. K. V.S. Meyer,
Manager, Outside Mines,
Cominco Ltd.,
Trail, B. C.

Dear Sir:

Re: Surface Openings - Sunro Mine

An inspection was made yesterday, in company with Mr. A. J. Richardson of your company, of surface openings at the Sunro mine. It was found that a total of seven openings had been sealed with timber and 3 - inch planking. (It was noted that an eighth opening, an ore pass, had been effectively sealed with steel rails.)

This sealing should prove satisfactory as a means of deterring persons from entering the underground workings as long as the seals remain intact. Mr. Richardson has advised that an inspection would be made by your company of the various seals at least once a year to ensure that they remain effective.

The work undertaken by your company to ensure that conditions at the Sunro mine have been left in a satisfactory condition with regard to safety of the public is appreciated.

Yours truly,

W. C. Robinson

W. C. Robinson, P.Eng.,
Inspector of Mines &
Resident Engineer

WCR/ep

c.c. Mr. A. J. Richardson ✓
Mr. J.E. Kerrett

