

WOBD

Scanned 10/2/2026, 5:30:16 PM

2001 Chrysler PT Cruiser

Web On-Board Diagnostics · Scan report

Check engine light: OFF · 1 code found

Code	Title	Urgency	What it means
P0601	Internal Control Module Memory Check Sum Error	UNKNOWN	The ECU's internal memory checksum does not match the expected value at startup – the firmware/calibration in flash has become corrupt. Often appears after a failed flash, low battery during programming, or genuine module hardware failure.

P0601 · Internal Control Module Memory Check Sum Error

Urgency: Unknown. I can't rate this one. If the car drives differently, get it checked.

Common causes:

- Failed flash / interrupted programming
- Module hardware failure
- Module software outdated, reflash may resolve

DIY or shop: Shop job

Tell your mechanic: "I have a P0601, Internal Control Module Memory Check Sum Error. Can you diagnose it?"

WOBD gives general information, not a professional diagnosis. Always confirm a problem before replacing parts.

WOBD is in active testing and development, and its results aren't guaranteed yet.

Free car diagnostics at wobd.app