Maintenance Log Entry

• **Date:** 2025-02-04

• **Technician:** Jamie R.

• Machine Type: CNC Lathe (Model: LT-200)

• Failure Type: Tool Wear Failure

• Error Code: TWF-007

Symptoms:

• Noticeable degradation in part surface finish.

- Increased vibration and occasional tool chatter during cutting.
- Slightly elevated spindle noise.

Diagnostic Steps:

- 1. **Visual Inspection:** Examined the cutting tool and confirmed significant wear on the edges.
- 2. **Sensor Review:** Analyzed vibration data which correlated with the wear signs.
- 3. Coolant Check: Verified coolant flow; confirmed it was within normal parameters.

Final Resolution:

- Tool Replacement: Removed the worn tool and installed a new, calibrated cutting tool.
- **Parameter Adjustment:** Fine-tuned spindle speed and feed rates for optimal performance.
- **System Reset:** Cleared error TWF-007 and conducted a brief test run to confirm stability.

Recommendations:

- Regular Inspections: Implement visual tool inspections every 30 operational hours.
- Vibration Monitoring: Continue tracking vibration data to detect early signs of wear.
- **Usage Logs:** Maintain a log of tool usage hours to anticipate and schedule timely replacements.