Part No.	Ą	A40-R								Heat Lot/Traceability	ility	
Order No.	40	400689	1	U	devices, LLC	Ċ		Con	Component(s)	No(s)		
Order Qty		2							A40	110		
	Distingu	Distinguishing Traceablity Numbers	lity Numbers					200	A-RING	100033	8	
Flare Nuts	Six digit no.	Six digit no. located on the box label under box quantity.	box label un	der box qu	antity.					8		/
Brazing Rings	Located on	Located on the box label, directly above the word "heat."	directly above	the word	"heat."							
Copper Tubing	Located on	Located on the spool label, starting with the letter "M."	, starting with	າ the letter	"M."							
Flare Tubes	Use their wo	Use their work order number and date on the box label	per and date	on the box	label.							
Snap Rings	Located on	Located on the bag followed by "Lot Number."	ed by "Lot Nu	mber."								
Caps/Plugs	Do not requ	Do not require traceability.										
	A SERVICE OF SERVICE AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IN COLUMN TO ADDRESS OF THE PERSON NAMED IN COLUMN TWO IN COLUMN TO ADDRESS OF THE PERSON NAMED IN COLUMN TWO IN COLU	· · · · · · · · · · · · · · · · · · ·										
Mach. No.			Setup Hrs.	1 0	Cycle Time			Pcs./Hr		Thru- put/8hrs		
Date Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total		Down Time D	Down Time Code			Notes		Scrap	Scrap Code
2/16 m		9										
									7	5		
									9	Si		
				-							P	
ROUTING:				L							(
Special Notes / Instructions	uctions	Down Time (Codes				F	First Part Ir	irt Inspection Record			
		 Maintenance Tooling 	Date Subr	Date Part Time	Time Of Day A	Approved Yes / No	Mtrl R	Rev Letter	Inspector	Notes	esti .	
						\vdash						
	4 13		T									
BBAZING BBODILOTION BEO		6 Meeting										
BRAZING PRODUCTION RECORD	ORD										Test F	Test Form 11/4/15