Test Form 11/4/15	Test F								RD	BRAZING PRODUCTION RECORD	BRAZING PRO
					The second second			Meeting			
					XES	18:35	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	Setup FAIR Training	5 4 5		
	Notes	N	Inspector	1	Approved M Yes / No Ch	Time Of Day	Date Part Submitted	Maintenance Tooling	2 1		
			Inspection Record	First Part In			\$	Down Time Codes	tions	Special Notes / Instructions	Specia
	3				Name of Street or other Party of Street, or						ROUTING:
	\$										
)										
		3									
			200								
			7								
					*					ă i	
						/	((1 1.1
						0	119	18	のまり	S	MEERE
Scrap	Scrap		Notes		Down Time Code	Down Time [Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs				Time	Hrs.	=			
		Thru-		Pos /Hr		Cycle	Setup	Se		Mach. No.	
		14	CP13					Do not require traceability.	Do not requi	Caps/Plugs	Caps
			BRZ04			` =	y "Lot Number.	Located on the bag followed by "Lot Number."	Located on t		Snap
			CUTU-17-3/16	CUT		box label.	and date on the	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
			BRZ03			etter "M."	rting with the I	Located on the spool label, starting with the letter "M."	Located on t	Copper Tubing	Coppe
			TU-1.875-1/2	CUTI		vord "heat."	ctly above the v	Located on the box label, directly above the word "heat."	Located on t	Brazing Rings	Brazir
			L-RING			ox quantity.	k label under bo	Six digit no. located on the box label under box quantity.	Six digit no. I	Flare Nuts	Flan
			に			115	Numbers	Distinguishing Traceablity Numbers	Distingui		
			SF404-8-3/16	SF4				100	10	Order Qty	Ord
	1	No(s)	Component(s)	Con	LC	devices, LLC	T T	399804	399	Order No.	Ord
	eability	Heat Lot/Traceability						S404-8-3/16217F	S404-8-3	Part No.	Par