									5 Meeting	6		
			2							4 n		
		1	Δ							ω		
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted		 Maintenance Tooling 	2 1		
		t Part Inspection Record	First Part I					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
												ROUTING:
	7											
\ 	P											
		-										
		11										
		7										
	Small	100	7	2110x	. ,							
Scrap Code	Scrap	Notes			Down Time Code	Down Time	Cum. Total	Cun	Total Pcs.	Prod Hrs.	Emp. Name	Date
No. of Contract of	put/8hrs					lime		nrs.				
	Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
								×	Do not require traceability.	Do not requ	Caps/Flugs	Caps
							טר ואטוווטפו.	יבט אין בי	cocated on the pag followed by For Namber.	rocated of	Clap Miles	0 1 9
		5				1 20% 10201	adec off effe		the bee fellow	l postad on	Dist	2
		CB15				hox lahel	date on the	her and	Use their work order number and date on the hoy label	Use their w	Flare Tubes	Flare
		CUTU-0-7/8	C			etter "M."	g with the l	l, starting	Located on the spool label, starting with the letter "M."	Located on .	Copper Tubing	Coppe
		BRZ05				ord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
		BRZ09				x quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
		CUTU-0-1/4	Ct				bers	olity Num	Distinguishing Traceablity Numbers	Distingu		
		7-4-9							1		Order Qty	Orde
	No(s)	Component(s)	Cor		LLC	devices, I	H		393200	39	Order No.	Ord
	Heat Lot/Traceability)			1			7-7-7-1	- 10	41.61.40.	