Test Form 11/4/15	Те									) R	BRAZING PRODUCTION RECORD	BRAZING PR
									, and a second			
									Meeting	6 U		
					_				FAIR			
									Setup			
	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2		
			First Part Inspection Record	First Part Ir					Down Time Codes		Special Notes / Instructions	Specia
												ROUTING:
	Q	(										
	2	ST										
		+			1							
			1									
	2											
											į	
									u		SOS	1/27
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
10000000000000000000000000000000000000		put/snrs					ilme		nis.			
		Thru-		Pcs./Hr			Cycle	n p	Setup		Mach. No.	
					_						1000	
									traceability.	Do not require traceability.	Caps/Plugs	Cap
							=	"Lot Number.	Located on the bag followed by "Lot Number."	Located on the	Snap Rings	Sna
11							box label.	nd date on the	Use their work order number and date on the box label.	Use their work	Flare Tubes	Flare
							etter "M."	ting with the l	Located on the spool label, starting with the letter "M."	Located on the	Copper Tubing	Coppe
							vord "heat."	tly above the w	Located on the box label, directly above the word "heat."	Located on the	Brazing Rings	Brazi
							ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no. lo	Flare Nuts	Flar
	ZIA	7	G-RING	500				lumbers	Distinguishing Traceablity Numbers	Distinguish		
	793934	S.	G6							2	Order Qty	Ord
	No(s)	7	Component(s)	Cor		LLC	devices, LLC	£	67	398367	Order No.	Ord
	Heat Lot/Traceability	Heat Lot/					Ont no		20	G6-R	Part No.	Pa