Test Form 11/4/15	Tе									ORD	BRAZING PRODUCTION RECORD	BRAZING PRO
			-						6 Meeting			
	600		11		S.	-	ı		5 Training			
	(EOMAO)	- T	A	9	52h	Br	1-14-16		3 Setup			
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	ice	 Maintenance Tooling 			
		Inspection Record	First Part Ir			SEN SELECT		ne Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
												ROUTING:
	7											
	527											
										_		
								+				
								+	L			
								+				
								+				
												9
	8					C			_	30 min	4	1/18/16
Scrap Code	Scrap	Notes			Down Time Code	Down Time	Cum. Total	Cr	Total Pcs.	Prod Hrs.	Emp. Name	Date
	pulyonis						Service Control		ON MANAGEMENT OF	The second second	Charles and the same of the sa	
	Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
					TO A STATE OF THE PARTY OF THE		Million College College					
***************************************								lity.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
W-Gravens		L-RING				а	Located on the bag followed by "Lot Number."	owed by "	the bag foll	Located on	Snap Rings	Snap
		L1/2		l.		box label.	Use their work order number and date on the box label.	ımber anc	ork order nu	Use their w	Flare Tubes	Flare
		BRZ03		l		etter "M."	Located on the spool label, starting with the letter "M."	bel, startii	the spool la	Located on	Copper Tubing	Coppe
		BRZ05				vord "heat."	Located on the box label, directly above the word "heat."	el, directly	the box lab	Located on	Brazing Rings	Brazir
		CUTU-1-1/2	CU			x quantity.	Six digit no. located on the box label under box quantity.	the box la	located on	Six digit no.	Flare Nuts	Flare
		CUTU-12-1/4	CU.				mbers	ablity Nu	Distinguishing Traceablity Numbers	Distingu		
	397068	SF405-3-1/4-1/2	SF40						1		Order Qty	Orde
	No(s)	Component(s)	Con		LLC	devices, LLC	H		397068	58	Order No.	Orde
	Heat Lot/Traceability					ont not			KF990005-01	KF99	Part No.	Par