DUPLICATE-SORRY

									ı			
									5 Meeting	6 U		
										ω 4 τ		
Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted			2 1		
		Inspection Record	First Part Ir	11				Codes			Special Notes / Instructions	Special
												ROUTING:
					,							
		Notes			Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
		BRZ31						,	Do not require traceability.	Do not requ	Caps/Plugs	Caps,
		BRZ24					ot Number.	ed by "Lo	Located on the bag followed by "Lot Number."	Located on t	Rings	Snap Rings
		CUTU-12-3/16	CUT			box label.	date on the	ber and o	Use their work order number and date on the box label.	Use their wo	Tubes	Flare Tubes
		CH-301				etter "M."	with the le	l, starting	Located on the spool label, starting with the letter "M."	Located on t	Tubing	Copper Tubing
		CH-201				ord "heat."	bove the w	directly a	Located on the box label, directly above the word "heat."	Located on t		Brazing Rings
		CH-101			440	x quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.		Flare Nuts
		CSW-3/8	0				bers	olity Num	Distinguishing Traceablity Numbers	Distingu		
		CH01-8-3/16	СН						200	2	· Qty	Order Qty
No(s)	No	mponent(s)	Con		LC	devices, LLC	7		392807	397	r No.	Order No.
Traceabil	Heat Lot/Traceability	amount/ol				201			CU01-9-1/10-17	CUOT-0	140.	Part No.