Test Form 11/4/15	Test										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
	Notes		Inspector	Rev Letter	Check	Approved Yes / No	Time Of Day	Submitted	lance	<ol> <li>Maintenance</li> <li>Tooling</li> <li>Setup</li> </ol>			
			Inspection Record	First Part I					Down Time Codes		ctions	Special Notes / Instructions	Specia
													ROUTING:
	F							1					
	>	S											
		かい							+				
		010							+				
		740											
									+				
													ži,
										35		SS	100
Scrap Code	Scrap		Notes		11.00	Down Time Code	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs		Pcs./Hr			Time	7	Hrs.			Mach. No.	
	The state of the s					A PRINCIPLE OF			Cott	Agent layour panet	Merchan Display	Control of the Woods	
					L				bility.	Do not require traceability.	Do not req	Caps/Plugs	Сар
	ı						Ē	Located on the bag followed by "Lot Number."	ollowed by	the bag fo	Located or	Snap Rings	Snai
							e box label.	Use their work order number and date on the box label.	number ar	vork order	Use their v	Flare Tubes	Flare
							etter "M."	ocated on the spool label, starting with the letter "M."	label, start	the spool	Located or	Copper Tubing	Coppe
						# ·	vord "heat.'	ocated on the box label, directly above the word "heat."	ıbel, direct	the box la	Located or	Brazing Rings	Brazi
							ox quantity.	Six digit no. located on the box label under box quantity.	n the box	). located o	Six digit no	Flare Nuts	Flar
	20293300	202	A-RING					umbers	ceablity N	Distinguishing Traceablity Numbers	Disting		
	2 >	Z	A68							25		Order Qty	Ord
	No(s)	7	Component(s)	Col		LLC	devices, LLC	H		397053	3	Order No.	Ord
	Heat Lot/Traceability	Heat Lot		,			7			A68-R	,	Part No.	Pa