Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PF
									ing Ing	6 Meeting			
									J				
		Notes	Inspector	Rev Letter	Mtrl	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling				
			t Inspection Record	First Part Ir			The state of the s		Down Time Codes		ctions	Special Notes / Instructions	Spec
													ROUTING:
	9												201
	7												
			15.										
) .	2	8									
		5											
									4			S &	12/11
Scrap Code	Scrap		Notes		- 1957	Down Time Code	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
THE PERSON NAMED IN		put/onis					IIIIe		- 1113:	Contract of the last			
		Thru-		Pcs./Hr			Cycle	5	Setup			Mach. No.	
									1000年の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の		Annual Property		
									eability.	quire trac	Do not require traceability.	Caps/Plugs	Cap
							`s	Located on the bag followed by "Lot Number."	followed by	n the bag	Located o	Snap Rings	Sna
							box label.	Use their work order number and date on the box label.	er number ar	work orde	Use their v	Flare Tubes	Flar
							etter "M."	Located on the spool label, starting with the letter "M."	ol label, stan	n the spo	Located o	Copper Tubing	Copp
							vord "heat."	Located on the box label, directly above the word "heat."	label, direct	n the box	Located o	Brazing Rings	Braz
							ox quantity.	Six digit no. located on the box label under box quantity.	on the box	o. locatec	Six digit no	Flare Nuts	Fla
		991407PP	J-RING	1				umbers	Distinguishing Traceablity Numbers	guishing T	Disting		
	_[N/A	J1-1/2	q	B					7		Order Qty	Ord
		No(s)	Component(s)	Cor		ררכ	devices, LLC	H		393739	ω	Order No.	Or
	lity	Heat Lot/Traceability					7			J1-1/2-R	زر	Part No.	Pa