									6 Meeting			
	Notes	inspector	KeV Letter	Check	Yes / No	Time OT Day	Submitted		2 Tooling 3 Setup			
				Mtrl	Approved	i D	Date Part		1 Maintenance			
		t Inspection Record	First Part I					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
0												
?	`											
	25											
				1								
12												
										ลำ		
											,	
									35		38	1/12
Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs			Name of Street	The second second	Time		Hrs.				
	Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
L								×	Do not require traceability.	Do not requ	Caps/Plugs	Cap
						Ψ.	ot Number.	ved by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snaj
						box label.	date on the	ber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
			io.			etter "M."	g with the le	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						ord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
						x quantity.	າel under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
	2	C-RING					nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
	396713	CR10		112					35		Order Qty	Ord
	No(s)	Component(s)	cor		LLC	devices, LLC	7		396630	39	Order No.	Ord
ΞŢ	Heat Lot/Traceability	sponost(c)	?			ontrol			CKIO-K	5	Part No.	Pa