Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
										3 Setup			
	×.	Notes	Inspector	Rev Letter	Mtrl	Approved Yes / No	Time Of Day	Date Part Submitted	ice	 Maintenance Tooling 			
			Inspection Record	First Part In					ne Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
	1												ROUTING:
	Z											-	
		9							1				
		H. Sy							+				
		?											
		10										1	
					+								
										دن		SB	3/8
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cı	Total Pcs.	Prod Hrs.	Emp. Name	Date
		Thru- put/8hrs		Pcs./Hr			Cycle		Hrs.			Mach. No.	
			Marin Charles Company of the Company		· · · · · · · · · · · · · · · · · · ·	a District of the last	The second second			NAME AND ADDRESS OF TAXABLE PARTY.	Property Section	The Court of the C	
									lity.	Do not require traceability.	Do not req	Caps/Plugs	Caps
			2				п	Located on the bag followed by "Lot Number."	owed by '	the bag follo	Located on	Snap Rings	Snap
							box label.	Use their work order number and date on the box label	ımber anı	ork order nu	Use their w	Flare Tubes	Flare
							etter "M."	Located on the spool label, starting with the letter "M."	bel, starti	the spool la	Located on	Copper Tubing	Coppe
						1950	vord "heat."	Located on the box label, directly above the word "heat."	ા, directly	the box labe	Located on	Brazing Rings	Brazir
		30140766	J-RING				ox quantity.	Six digit no. located on the box label under box quantity.	the box la	. located on	Six digit no	Flare Nuts	Flan
)():			J2-1/2					mbers	ablity Nu	Distinguishing Traceablity Numbers	Disting		
		399705	502-5-3/16	50						3		Order Qty	Ord
	1	No(s)	component(s)	G		LLC	devices, LLC	T.		399721	35	Order No.	Ord
	ility	Heat Lot/Traceability		2			55+50	J		502-5-3/16-2.5	502-5	Part No.	Par