Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
		Notes	Inspector	Kev Letter	Check	Yes / No	Time Of Day	Submitted					
					Mtrl	Approved		Date Part	ro i	1 Maintenance			
	THE PERSON		rt Inspection Record	First Part In					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	0												
	P						1	1					
		9	V										
		000	1										
		,			_								
				30									
									+				
								NO DO	6			8	5.11.6
Code	aciab		10000			Code	DOWN THIE					11.70	2
Scrap	Coran		Notes			Down Time	Down Time	Cum. Total	<u> </u>	Total Pre	Prod Hrs	Fmp. Name	Date
		put/8hrs					Time		Hrs.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
									₹	Do not require traceability.	Do not rear		Caps
							<b>a</b>	ot Number.	wed by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snar
							box label.	date on the	mber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
					J. ·	1	etter "M."	ng with the le	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
					ı	and the second s	vord "heat."	above the w	l, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazin
							x quantity.	bel under bo	he box lat	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
			G-RING					nbers	ablity Nun	Distinguishing Traceablity Numbers	Distingu		
\			GR5							2		Order Qty	Ord
		No(s)	Component(s)	Con		LLC	devices, LLC	1		400698	40	Order No.	Ord
		Heat Lot/Traceability		}			on tool	ı		GR5-R	G	Part No.	Pai